

NEW MEXICO OIL AND GAS COMMISSION

C-102 and C-103
Effective 1-1-65

| | |
|-------------|--|
| DATE | |
| NAME | |
| S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
Salt Mining Lease

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Salt Well | 7. Unit Agreement Name |
| 2. Name of Operator Truckers Water Co. | 8. Farm or Lease Name Truckers Water Co. |
| 3. Address of Operator P. O. Box 1196, Eunice, New Mexico 88231 | 9. Well No. #2 |
| 4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18S</u> RANGE <u>38E</u> NMPM. | 10. Field and Pool, or Wellcat |
| 15. Elevation (Show whether DF, KT, GR, etc.) 3637 Gr. | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JQB <input type="checkbox"/> |
| OTHER <input type="checkbox"/> | OTHER <input type="checkbox"/> |
| PLUG AND ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled plug from surface to 25', washed muddy water from 25' to 2600'. Went in hole and tagged cement plug at 2935', set 7000# wt. on plug at 2935'. Tested csg w/1000# for 30 minutes. Held OK. Rigged up Dresser Atlas and pert total of 20 holes from 2400 - 2410 and 20 holes 2060 - 2070. Baker loc - set PKR and set at 2100'. Pressured perms at 2060 - 70 w/1500# and established circulation behind csg. Rigged down unit and started washing behind csg with fresh water. Max Press 1300# - min 3800#. Completed as a brine well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED AG Brakey TITLE Vice-President DATE 12-1-60

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: