


SCOUT REPORT NEW MEXICO OIL CONSERVATION COMMISSION



Company		D. D. Thomas		
Farm Name		Stroup	Well No. 2	
Land Classification		Government		
Sec. 12	Twp. 18	Range 32	County Lea	
Feet from Line: 1980 N.		S. 1980	E.	W.
Elevation 3879		Method		
Contractor		Scout		
Spudded 12-6-30		Completed 6-20-31	Initial Production	
Bond Status				

**Amount
Casing and Cementing Record**

SIZE	FEET	INCHES	BOX CEMENT
10"	798		S
8 1/4"	1235		S
7"	3740		100
5 1/2"	4079		50

ACID RECORD

Gals.

Top Pay

TD

TA 1320
TX 1440
BX 2635
TRS
TY 2795
TBL 2645 ?
TWL

Tubing Record

Packer

SHOOTING RECORD

No. of Quarts 380	From 4019	To 94
No. of Quarts	From	To
S/	S/	S/
S/	S/	S/

DATE	10-12-39 Cellar and Pits	DATE	
11-15	Road	3-13	Ø 1975 X
12-6	RU	3-20	Ø 2735 L
12-13	TD 50' RB	3-29	Ø 2812 L
	SD Bond	4-3	TD 2900 L SDR
12-20	Ø 102 RS	4-10	Ø 3180 L
12-28	TD 520 RR		SS/A 3000-10 L
	SDR S/W 275-95 S	4-17	Ø 3355 L S/D 3350-42 L
1-4-40	TD 520 RR prep to Ø	4-24	Ø 3525 L
	S/W 360 S	5-1	TD 3680 L SDR
1-10	TD 685 R-	5-3	Ø 3817 sdy L
	CO @ 660	5-15	Ø 3925 L
1-17	TD 695 S CO & Rev	5-22	TD 4055 S SD
	last hit in hole	5-28	TD 4055 S SD
1-24	TD 795 sdy L Fish tail	6-18	TD 4080 S
	S/W 765 S		SLM 4055 = 4037
1-31	TD 795 S + L		600' X/W/H in / to 4078-80 S
2-7	Ø 1035 sdy -	6-18	TD 4100 L SD Jan SLM Rep
2-14	TD 1235 RR 4 - Eng 8 1/4"	7-2	TD 4100 L prep in 7" SD
2-21	TD 1325 A SDR	7-17	TD 4093 L
2-28	TD 1325 A	7-24	TD 4093 L under survey
3-6	TD 1480 X SD Ingle	7-31	TD 4093 L SPO

LOG

Depth	Formation	Depth	Formation	Depth	Formation
	U.R. to bottom	6-11	TD 4300 L.D.D.		
8-7	TD 4093 2	6-18	TD 4500 V.K.		
	prep & encsg to bottom	6-25	TD 4500 (A+V)		
	2000' F.I.H.				
10-9	TD 4110 Rv cond				
	S.D.D.				
	S/W 4060-655				
10-15	TD 4110 Rv. S				
	tailing w/ load				
	shot 380 4019-4094				
10-23	TD 4110 Rv. S				
	S.D.D. H.F.D.				
11-06	TD 4110 S				
	W.O. Csg.				
	H.F.F. lined				
12-4	TD 4110 S				
	prep & run csg				
12-11	TD 4110 S				
	prep & plug				
12-18	TD 4110 S				
	prep & cement				
	lot 20 BWPH				
12-30	TD 4110 S				
1-8-21	TD 4110 L.P. & P				
1-15	TD 4110 S log				
1-22	TD 4110 S				
	linking tools				
2-19	TD 4110 S				
	S.D.D.				
3-19	✓				
	TD 4110 S				
	joby tool				
4-9	TD 4110 2				
	shot @ 4070				
4-23	TD 4110 2				
	plug				
4-30	TD 4175 4				
	plug cement job				
5-7	TD 4110 S				
	prep w/ squeeze job				
6-4	TD 4110 S				
	M.R. to deepen				

