

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B 4286
7. Lease Name or Unit Agreement Name West Lovington Unit
8. Well No. 5
9. Pool name or Wildcat <i>upper</i> West Lovington-San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3899 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER Injection

2. Name of Operator
GREENHILL PETROLEUM CORPORATION

3. Address of Operator
11490 Westheimer, Suite 200, Houston, Texas 77077

4. Well Location
Unit Letter C : 1980 Feet From The West Line and 660 Feet From The North Line
Section 4 Township 17S Range 36E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Run pressure chart.</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU pump trunk to casing and pressure up to 385#. Ran chart for 30 minutes. Ending pressure-385#. Release pressure and RD pump truck. RDPU. Empty frac truck. Cover up pit and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael Newport TITLE Land Manager-Permian Basin DATE 11-14-91

TYPE OR PRINT NAME: Michael J. Newport TELEPHONE NO. 713 589-8484

This space for State Use) Orig. Signed by Paul Kautz Geologist

APPROVED BY _____ TITLE _____ DATE NOV 19 1991

CONDITIONS OF APPROVAL, IF ANY: _____

