

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-20116
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McCallister State
8. Well No. 5
9. Pool name or Wildcat Vacuum; Blinebry
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4007' GL 4019' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Marathon Oil Company
3. Address of Operator P.O. Box 2409, Hobbs, NM 88240
4. Well Location Unit Letter M : 660 Feet From The South Line and 560 Feet From The West Line Section 25 Township 17S Range 34E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4007' GL 4019' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Rull RPB to DHC Vac; Blinebry, Abo, Wolfcamp <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/21 MIRU pulling unit. POOH w/pump & rods.
 5/22 ND wellhead. Re1 TAC. NU BOP. TOOH w/2 7/8" prod tbg. RIH, tag fill at 7342'. Clean out to 7495'.
 5/23 Re1 RBP at 7500'. POOH w/RBP.
 5/27 RIH w/2 7/8" prod tbg. Test tbg, OK. ND BOP. Set TAC. NU wellhead. RIH w/pump & rods.
 RD pulling unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Kelly Cook* TITLE Records Processor DATE 9/10/98
 TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)
 ORIGINAL SIGNED BY CHRIS WILLIAMS
 DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: