

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

14. Indicate Type of Lease
State Free

15. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL GAS WELL OTHER _____

2. Name of Operator
Amoco Production Company

3. Address of Operator
P. O. Box 68, Hobbs, New Mexico 88240

4. Location of Well
SL 580
UNIT LETTER M BHL 1310 South 1310
THE West LINE, SECTION 3 TOWNSHIP 19-S RANGE 38-E NMPM.

7. Unit Agreement Name
8. Form or Lease Name
South Hobbs (GSA) Unit
9. Well No.
144
10. Field and Pool, or Wildcat
Hobbs GSA

11. Elevation (Show whether DF, RT, CR, etc.)
3609.6' GL

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER plug back, kick-off & Redrill to target <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Trip in hole with diverting tool and 4-1/2" drill pipe to 4484'. Circulated hole. Spot first cement plug 250 sx class H from 4484'-3900'. Pulled up to 2900' and spot second cement plug 125 sx class H from 2900'-2700'. Pulled up to 2100' and spot third cement plug 375 sx class H with additives from 2100' to 1700'. POH and WOC 18 hrs. Trip in hole and tag cement at 1460'. Drilled out stringers and cement to 1705'. Kicked-off cement plug at 1705' and resumed drilling to target location.

O+4-NMOCD, H 1-HOU, R. E. Ogden, Rm 21.150 1-F. J. Nash, HOU Rm 4.206 1-CMH 1-Texaco
1-Shell 1-Sun 1-Petro Lewis

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Herring TITLE Administrative Analyst DATE 10-4-83

APPROVED BY _____ TITLE _____ DATE OCT 11 1983

CONDITIONS OF APPROVAL, IF ANY: