

Submit 3 Copies To Appropriate District Office
 District I 1625 N. French Dr., Hobbs, NM 87240
 District II 811 South First, Artesia, NM 87210
 District III 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO. 30-025-06831
5. Indicate Type of Lease STATE <input type="checkbox"/> FBE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: J. N. CARSON (NCT-C)
8. Well No. 3
9. Pool name or Wildcat TUBB(GAS) / DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150 Midland, TX 79702	4. Well Location Unit Letter P ; 640 feet from the SOUTH line and 660 feet from the EAST line Section 28 Township 21S Range 37E NMPM County LEA
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

POH W/TBG. SET CIBP @ 6400', SPOTTED 35' CMT ON TOP; TAGGED @ 6300'. PERFD @ 2951', ATTEMPTED TO CIRC - UNABLE TO PUMP INTO PERFS (MR. GONZALES W/OCD OK'D). PPD 393 SX CMT TO SURF IN 9-5/8". CLOSED VALVE, PRESS UP TO 700#, DISP CMT OUT TBG INTO 7" CSG. TAGGED PLUG @ 2339'. SPOTTED 40 SX CMT @ 1310'; TAGGED @ 1054'. PERFD 240'-354' W/ 4 JHPF. PPD 140 SX CMT DN TBG & UP 13-3/8". FILLED W/CMT, PPD TO SURF. SET MARKER, CLEANED LOCATION.

P&A'D 9/10/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE REGULATORY O.A. DATE 9/25/01
 Type or print name J. K. RIPLEY Telephone No. (915)687-7148

APPROVED BY [Signature] TITLE fld Lep DATE 2-28-02
 Conditions of approval, if any: GW