

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-07000

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

~~Eva~~ Owen "B"

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
5

2. Name of Operator
Amoco Production Company

9. Pool name or Wildcat

3. Address of Operator
P. O. Box 3092; Houston, Texas 77253

4. Well Location
Unit Letter L : 1830 Feet From The South Line and 440 Feet From The West Line

Section 34 Township 21-S Range 37-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3454' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING OTHER:
SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI-RUSU 12/5/88. Pulled production tubing, set CIBP at 3770' and capped with 35 sacks of cement. Ran casing guns and perforated at 3000'. Established circulation. Pressure tested casing to 500 psi. Ran cement retainer and set at 2845', R.U. HOWCO and cement squeezed with 350 sacks Class C neat cement. Circulated hole with 9.5 lb/gal brine mud. Spotted 25 sacks Class C cement 2510'-2269'. Pull tubing and spot 25 sacks Class C cement 1175'-934'. Pull tubing and spot 25 sacks Class C cement 375'-134'. Pull tubing and spot 20 sacks Class C cement surf. plug. Nippled down BOP and dug out cellar. Cut off wellhead and welded on plate. No PxA marker per agreement with Eddie Seay. Rig down service unit 12/7/88 and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steven J. Kuchler TITLE Sr. Admin. Analyst DATE 12/10/88

TYPE OR PRINT NAME Steven J. Kuchler TELEPHONE NO. 713-584-732,

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE FEB 15 1989

CONDITIONS OF APPROVAL, IF ANY:

8