

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St. Santa Fe, 87505

WELL API NO. 30-025-07017

5. Indicate Type of Lease STATE [] FEE [X]

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

MARSHALL COM

1. Type of Well: OIL WELL [X] GAS WELL [] OTHER []

8. Well No.

6

2. Name of Operator Titan Resources I, Inc.

3. Address of Operator 500 West Texas Suite 500, Midland, TX 79701

9. Pool name or Wildcat Paddock

4. Well Location Unit Letter E : 2230 Feet From The North Line and 330 Feet From The West Line Section 34 Township 21-S Range 37-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3464' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] OTHER: []

SUBSEQUENT REPORT OF:

REMEDIAL WORK [X] ALTERING CASING [] COMMENCE DRILLING OPNS. [] PLUG AND ABANDONMENT [] CASING TEST AND CEMENT JOB [] OTHER: []

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out and acidize Paddock perfs 2/3/97 MIRU pulling unit. POOH with rods, pump and tubing. RIH with clean-out bailer on tubing. 2/4/97 Cleaned out to 5312 ft. (Perfs: 5151' - 5289'). Recovered iron sulfide scale and paraffin. RIH with packer, set at 5112'. Swabbed well down. 2/5/97 Acidized perfs 5151' - 5289' with 3000 gal 15% NEFe HCl and paraffin chemical. Swabbed well. Recovered paraffin, iron sulfide and oil emulsion. 2/6/97 Made 3 swab runs--65% oil. POOH with tubing and packer. RIH with 2-3/8" tubing for production. RIH with pump and rods and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Project Manager DATE 2/24/97 TYPE OR PRINT NAME Ron Lechwar TELEPHONE NO. 915/682-661

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR

MAR 04 1997

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: