

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22245

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
McGarrity

8. Well No. 1

9. Pool name or Wildcat
East Weir Blinbry

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
TEAM Exploration

3. Address of Operator
C/O OIL REPORTS & GAS SERVICES
P.O. Box 755, Hobbs, NM 88241

4. Well Location
Unit Letter N : 660 Feet From The South Line and 2310 Feet From The West Line
Section 6 Township 20S Range 38E NMPM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3579 KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Add additional Blinbry perfs</u> <input type="checkbox"/>		OTHER: <u></u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Shot Blinbry -6280, 79, 73, 72, 71, 70, 62, 61, 60, 59, 58, 07, 06; 6185, 83, 76, 75, 56, 55, 54, 53, 52, 51 (46 holes-2 SPF)
- Set CIBP @ 6291.
- RU BJTitan w/3000 gals 20% HCL & acidized w/PPI tool, swabbed back load
- Squeezed off lower Paddock perfs from 5791-5887 w/400 sx Class C cement. Drilled out, tested 800#. Tested OK.
- Shot additional Blinbry 6091, 87, 84, 10, 09, 08; 5991, 90, 89, 74, 29, 20, 19, 18, 17, 16, 06; 5899, 98, 97, 94.
- RU BJTitan w/3000 gals 15% HCL & 500 gals solvent. Treated new perfs w/PPI tool.
- Swabbed back 120 bbls of load & placed on pump. Making 10-15% oil cut & unknown amount of gas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donald A. Turner TITLE President DATE 10-19-92
TYPE OR PRINT NAME Donald A. Turner TELEPHONE NO. 915/682-3418

(This space for State Use)
APPROVED BY Paul Kautz Geologist TITLE _____ DATE _____
OCT 21 '92
CONDITIONS OF APPROVAL, IF ANY: