

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34143

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

FRED TURNER A

15

8. Well No. 15

9. Pool name or Wildcat
SKAGGS/ABO EAST

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
<p>1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p>	
<p>2. Name of Operator Amerada Hess Corporation</p>	
<p>3. Address of Operator P. O. Box 840, Seminole, Texas 79360-0840</p>	
<p>4. Well Location Unit Letter <u>I</u>: <u>2160</u> Feet From The <u>SOUTH</u> Line and <u>990</u> Feet From The <u>EAST</u> Line Section <u>18</u> Township <u>20S</u> Range <u>38E</u> NMPM LEA County</p>	
<p>10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3555' GR</p>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER:
- PLUG AND ABANDON
- CHANGE PLANS
- OTHER:

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER: Progress Report.
- ALTERING CASING
- PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-15 thru 12-16-97

MIRU Dawson Well Svc. & installed BOP. TIH w/4-3/4" bit, tagged ECP at 6805' & drld. out ECP & cement to 6816'. TIH, tagged cement at 7624' & drld. cement, FC at 7628' & cement to 7718'. Circ. hole clean. Halliburton Svc. ran CBL. Western Atlas TIH w/4" csg. guns & perf. 5-1/2" csg. w/2 SPF, total 17 shots fr. 7664' - 7672'. American Fracmaster acidized perfs. fr. 7664' - 7672' w/500 gal. 15% acid. Swabbed well. TIH w/5-1/2" CIBP & set at 7600'. TIH & spotted 2 sks. Class "H" cement on top CIBP. Western Atlas TIH w/4" csg. gun & perf. 5-1/2" csg. w/4 SPF fr. 7396' - 7400', 7410' - 7418', 7424' - 7428', 7436' - 7438', 7442' - 7444', 7460' - 7462', 7470' - 7472', 7495' - 7505', 7508' - 7520', 7538' - 7540', 7543' - 7548', 7552' - 7554', 7558' - 7566', 7569' - 7577', 7584' - 7586', & fr. 7611' - 7623'. American Fracmaster acidized perfs. fr. 7396' - 7623' w/3000 gal. 15% HCL w/6% Fercheck. Swabbed well. TIH w/5-1/2" CIBP & set at 7530'. CONTINUED OVER

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Admin. Svc. Coord. DATE 12-17-97

TYPE OR PRINT NAME Roy L. Wheeler, Jr. TELEPHONE NO. 915 758-6700

(This space for State Use)
APPROVED BY [Signature] TITLE SENIOR DATE 12-17-97
CONDITIONS OF APPROVAL, IF ANY: