

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO
NM 64602
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL GAS WELL OTHER Plugged and abandoned

2. NAME OF OPERATOR
Collins & Ware, Inc.

3. ADDRESS OF OPERATOR
303 W. Wall, Suite 2200, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980 FSL and 660 FWL of Sec. 26
Unit L

14. PERMIT NO. _____ 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3709.9

7. UNIT AGREEMENT NAME
Lincoln Federal Unit

8. FARM OR LEASE NAME

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Undes. Bilbrey Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 26, T-21-S, R-32-E

12. COUNTY OR PARISH
Lea

13. STATE
NM

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Abandon</u>	<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Field operations began November 5, 1991 to plug and abandon the Lincoln Federal well.

Ran and set a 7" CIBP at 10,160' with 15 sack plug (50') placing top at 10,110', cut 7" casing at 3300' K.B. Pulled out of the hole with 3300'.

Plug No. 1-60 sacks cement at 3410'. Tagged at 3170'.

Plug No. 2-50 sacks cement at 940'. Tagged at 798'.

Plug No. 3-20 sacks cement at surface.

Welded plate and dry hole marker. Tag and final plug witnessed by Mr. Andy Cortez with the BLM.

18. I hereby certify that the foregoing is true and correct

SIGNED James P. Brown TITLE Agent for Collins & Ware, Inc DATE 12/13/91

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 12-26-91

CONDITIONS OF APPROVAL, IF ANY: