

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSTRUCTION COMMISSION

Form O-10  
Revised 8-68  
Oil and Gas  
Division

SUNDRY NOTICES AND REPORT ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TO MOVE TO A DIFFERENT LOCATION. USE APPLICATION FOR PERMIT TO DRILL (FORM O-10) FOR SUCH PROPOSALS.

GAS WELL  OTHER- **Injection Well**

Name of Operator  
**Skelly Oil Company**

Address of Operator  
**P. O. Box 1351, Midland, Texas 79701**

UNIT LETTER **F** 1980 FEET FROM THE **North** LINE AND 1980

THE **West** LINE, SECTION **8** TOWNSHIP **23S** RANGE **37E**

13. Elevation (Show whether DF, RT, GR, etc.)  
**3329' DF**

See

Skelly Penrose "B" Unit

Skelly Penrose "B" Unit

62

Langlie-Mattix

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER \_\_\_\_\_

PLUG AND ABANDON

CHANGE PLANS

STATEMENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPERATIONS

CASING TEST AND CEMENTING

OTHER \_\_\_\_\_

SETTING PLUG

GRAB AND SAMPLE

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent well and formation names. If proposed work) SEE RULE 1103.

- 1) Move in workover rig.
- 2) Spot cement plug 3400-3500'.
- 3) Perforate 5-1/2" OD casing at 1100'.
- 4) Cement squeeze 5-1/2" OD casing perfs. at 1100' with 200 sacks cement.
- 5) Spot cement plug surface to 60'.
- 6) Install dry hole marker.

Note: All intervals not cemented will be filled with 10.2# mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

(Signed) **D. R. Crow** **D. R. Crow** **Lead Clerk**

2-3-75

SIGNED \_\_\_\_\_ TITLE \_\_\_\_\_

APPROVED BY **Joe D. Ramsey** TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: **John I. Sany.**