


ITEM	DESCRIPTION	A. B. CHANGE NO.	JOSLYN NO.	OTHER MFRS. NO.	NO. SUB.
a	double upset bolt s/aq. nut, round washer, and cotter key on short end, sq. nut and HF locknut on long end, 15 1/8" long (or length required.) wet process porcelain secondary spool insulator, 3" brown glaze.	7428			
b	required size conduit w/ servicehead(s) & req'd size & rated insulated conductors. Ref. DWG ES-18 Note: provide clamp and ground conduit parallel groove clamp, size req'd		4101		
d	secondary insulator clevis for 4" insulator			BURNBY STAINLS "06"	
f	3/8" thimbleye nut	65/0			
g	5/8" x 1 1/4" (or length req'd) straight thimbleye bolt w/aq. nut	55/2		ALUMINATION 6M36	X
h	transformer clevis mount bracket (sm11)			ALUMFORM 15M36	X
i	transformer clevis mount bracket (large)				
m	req'd size raintight disconnect & fuses, 3-phase, 600 V, Ref. DWG No. ES-18				
n	16" cross plate anchor (or size req'd)	X-16			
q	8-way expanding anchor (also req'd)	88135			
r	4" brown glaze wet process porcelain secondary spool insulator		10101		
u	5/8" x 7" thimbleye anchor rod w/nut (use valveye if req'd - change No. 5961)	5317 (AUT 5906P)			
va	3/8" high strength guy strand (10,800 lb.)				
vb	preformed guy grip for 3/8" guy strand	5010			
vd	5/8" x 10" angle thimbleye bolt w/nut	6823 1/2			X
ve	3"x3/16"x11/16" hole curved washer				
vf	6" - guy clamp w/3-1/2" bolts				
vg	medium size strain insulator				
vh	servicing sleeve for 3/8" guy strand	6454			
vi	3/16" x 2-1/2" x 7" lift plate	7887			X
vj	pole bottom ground plate (may use butt-wrapp if deleted)				
vk	Ground Connection (See DWG. ES-11)				
vl	wet process porcelain secondary spool insulator, 3" - white glaze				
vm	wet process porcelain secondary spool insulator, 4" - white glaze				

DATE: 12-27-71	TITLE: DESCRIPTION MATERIALS
DRAWN BY: E. WINTER	 HOBBS DIVISION
DESIGN BY:	
CHECKED BY:	
APPROVED BY:	
SCALE: NONE	PRODUCTION DEPT. JOB: ELEC SWGS DRAWING NO: ES-1 SHEET 5 OF 5