## KEURIVED

Submit 3 Copies To Appropriate District Office	State of N	Vew Me	xieo5 2004		Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals a			WELL API NO.	Revised March 25, 1999
District II	OIL CON RELY	MOITA	ANGERON TO		30-007-20522
811 South First, Artesia, NM 87210  District III  1220 South St Francis			5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	000 Rio Brazos Rd., Aztec, NM 87410 Sonto Es INIM 8778781			STATE U	FEE E
1220 S St Francis, Santa Fe, NM 87505			6. State Oil & C	Gas Lease No.	
SUNDRY NOT	ICES AND REPORTS ON	WELLS	RVATION	7. Lease Name of	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF THE BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				VPR B	
1. Type of Well:					VIII D
Oil Well Gas Well Other X Coalbed Methane				<u></u>	
2. Name of Operator  EL PASO ENERGY RATON, L.L.C.				8. Well No.	53
3. Address of Operator				9. Pool name or	Wildcat
P.O. Box 190, Raton, NM 87740				<u> </u>	
4. Well Location					
Unit Letter J: 1429 feet from the South line and 1643 feet from the East line					
Section 19 Township 30N Range 18E NMPM COLFAX County					
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 8512' (GL)					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	ITENTION TO:		1	SÉQUENT RE	
PERFORM REMEDIAL WORK $\Box$	PLUG AND ABANDON		REMEDIAL WORK	·	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRII	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND		/ID/IIIDONIALIA
OTHER:			OTHER:		COMPLETION
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
Procedure for Plug and Abandonment of VPR B 53 on 06-10-2004:					
Back 4 ½' drill pipe off at 931'. Set end of drill pipe at 900'. Break circulation. Mixed and pumped 27 bbls class H cement At 14 ppg. Displace with 5 bbls of water to balance plug. Pull drill pipe up to 450'. Pumped 35 bbls water displaced 2 bbls cement to the pit. Mixed and pumped 35 bbls of Trinidad surface blend 13 ppg. Circulated 1 bbl cement to pit. LD the 450' drill pipe. Mix up 8 bbls cement top hole off. Well standing full of cement. Install plugged well marker. Marked as follows: El Paso, VPR B 53, 1429' from the south line, 1643' from the east line, Sec 19, T 30N, R18E, Colfax County, New Mexico.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE	2/	TITLE_	Production Ma	nager DATE <u>0</u>	<u>6/14/04</u>
Type or print name: Donald R. Lankford Telephone No. (505) 445-6721					
(This space for State use)					
APPROVED BY 15 John TITLE DISTRICT SUPERVISORE 6/17/04					
Conditions of approval, if any:					