

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-021-20337
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. ...
7. Lease Name or Unit Agreement Name: Bravo Dome Carbon Dioxide Gas Unit 1933
8. Well Number 311
9. OGRID Number 16696
10. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas 640

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other CO2 Supply Well
2. Name of Operator OXY USA Inc.
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250
4. Well Location Unit Letter <u>G</u> : <u>1711</u> feet from the <u>north</u> line and <u>1793</u> feet from the <u>east</u> line Section <u>31</u> Township <u>19N</u> Range <u>33E</u> NMPM County <u>Harding</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>4798.4'</u>
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE David Stewart TITLE Sr. Regulatory Analyst DATE 10/29/04
Type or print name David Stewart E-mail address: david_stewart@oxy.com Telephone No. 432-685-5717

For State Use Only

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 11-2-04
Conditions of Approval, if any:

BDCDGU 1933-311

9/27/04

No Accidents Reported

MI & RUSU R 2.375 Tbg Swab Well Dry

9/28/04

P x LD Tbg RD & MOSU

Dump 8 BBL 15% HCL Acid with 8 BBL KCL

RU WL R 3.125 Perf Gun

Perforate 2424' to 2436' & 2450' to 2490' & 2510' to 2516

With 4 JSPF , .32" Holes 120 deg Phasing (244 Total holes)

Flow Well to Pit to Clean Up

9/29/04

Put well on Production

JK ok

10/14/04

Frac Down 5.50" Casing with 236 BBL gel KCL containing

461 sx 12/20 Brady Sand foamed with 36 Tons of CO2.

Max Press – 1732 psi Avg TP – 1300 psi AIR – 40 BPM

ISIP – 1000 psi 5 Min SIP – 573 psi 10 Min SIP 546 psi 15 Min SIP – 525 psi

Flow well on .5" Choke to clean up.

10/17/04

Put Well on Production