
	To Appropriate District	:38 PM	State of New Me	exico		Form C-1831			
Office <u>District I</u> – (575) 393-6161 Energy, N			Minerals and Natu	Minerals and Natural Resources		Revised July 18, 2013			
	Dr., Hobbs, NM 88240					WELL API NO. 30-015-41596			
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CON			ONSERVATION	ISERVATION DIVISION		Leace			
District III – (5		12	220 South St. Frai	ncis Dr.	5. Indicate Type of Lease STATE FEE □				
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505					Lease No.			
1220 S. St. Frai 87505	ncis Dr., Santa Fe, NM								
87303	SUNDRY NO	OTICES AND RE	PORTS ON WELLS	1	7. Lease Name or U	Jnit Agreement Name			
,	THIS FORM FOR PRO	OPOSALS TO DRILL	OR TO DEEPEN OR PL	UG BACK TO A					
PROPOSALS.)		PLICATION FOR PE	RMIT" (FORM C-101) FO	OR SUCH		CEDAR CANYON 16 STATE			
	Well: Oil Well 🔽	Gas Well	Other		8. Well Number 8	Η			
2. Name of	•				9. OGRID Number				
OXY USA INC					16696	7'1 1			
3. Address	•	NI TV 7704/	,		10. Pool name or W				
	4294, HOUSTC)N, TX, 77210)		PIERCE CRUSSING	G; BONE SPRING, EAST			
4. Well Loc	_	: 1040 fee	, Community NODTH	11	1	41. EAST 15			
	it Letter A		et from the NORTH	line and <u>33</u>		the EAST line			
Sec	tion 16		wnship 24S Range (Show whether DR	inge 29E		County EDDY			
		11. Elevano	II (Snow whether DK)	KKD, KI, GK, eic	.)				
	12 Chec	k Appropriate	Box to Indicate N	ature of Notice	Report or Other D	ata			
	12. Chec	k rippropriate	box to marcate 14	ature or riotice,	Report of Other D	ata			
	NOTICE OF	INTENTION	TO:	SUE	SEQUENT REP	ORT OF:			
PERFORM I	REMEDIAL WORK	PLUG AND	ABANDON 🗌	REMEDIAL WOR		LTERING CASING			
TEMPORAR	RILY ABANDON	☐ CHANGE PI	 -	COMMENCE DR	ILLING OPNS. P	AND A			
PULL OR AL	LTER CASING	☐ MULTIPLE (COMPL	CASING/CEMEN	T JOB				
DOWNHOLE	E COMMINGLE								
	OOP SYSTEM		_			_			
	DD PERFS/FRAC IN			OTHER:					
						including estimated date			
	arting any proposed osed completion or		LE 19.15.7.14 NMAC	. For Multiple Co	mpletions: Attach we	lbore diagram of			
prop	osca completion of	recompletion.							
-MIF	RU. POOH with pro	oduction equipn	nent						
				ut to 9,100' if ne	eded to isolate later	al			
	forate ~8,997' – 8	,559' and comp	lete in 2 stages						
-Flow well back -RIH with gas lift and tubing. RDMO and return well to production									
					to pressure of existi	na norforations			
	RU. POOH with pro			ure drawn down	to pressure or existi	ing periorations			
	anout plug and lat		iciic						
			nd return well to p	roduction					
]			7			
Spud Date:			Rig Release Da	ite:					
			<u> </u>						
I hereby certif	fy that the informati	on above is true a	and complete to the be	est of my knowleds	ge and belief.				
SIGNATURE	grily Messel		TITLE REGU	LATORY LEAD	DAT	E 04/09/2021			
SIGNATURE	- Nama &		1111111111111111111111111111111111		DAI	<u></u>			
Type or print	name EMILY MES	SSER	E-mail address	: EMILY_MESSE	R@OXY.COM PHO	NE: 713.497.2076			
For State Use									
	John Consis	.	Datrol	eum Specialist		4/15/2021			
APPROVED	BY: John Garcia	<u> </u>	TITLE_Petrol	specialist	DATI	3			
Conditions of	Approval (if any):								

OXY USA Inc. Cedar Canyon 16 State #8H API No. 30-015-41596

Current Wellbore




Perfs @ 9017-13407'

TD - 13560'M 8618'V

OXY USA Inc. Cedar Canyon 16 State #8H API No. 30-015-41596

Proposed wellbore



Perfs @ 8,585' - 13,407'

TD - 13560'M 8618'V

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 24210

CONDITIONS OF APPROVAL

Operator:		OGRID:	Action Number:	Action Type:
OXY USA INC P.O. Box 4294	Houston, TX772104294	16696	24210	C-103G

OCD Reviewer	Condition
jagarcia	None