
Office	tate of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 Energy, M	inerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	IGERAL TION DIVIGION	30-025-31423
811 S. First St., Artesia, NM 88210 OIL COI	NSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	anta Fe, NM 87505	6. State Oil & Gas Lease No.
87505		19552
SUNDRY NOTICES AND REPO (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM		South Hobbs G/SA Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Gas Well	other TEMPORARILY ABANDONED	8. Well Number 235
2. Name of Operator	TEINI OKAKIET ABANDONED	9. OGRID Number
OCCIDENTAL PERMIAN LTD		157984
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4294, Houston, TX 77210 4. Well Location		Hobbs; Grayburg - San Andres
	om the South line and 241	4 feet from the West line
	ship 19S Range 38E	NMPM County LEA
	Show whether DR, RKB, RT, GR, etc.,	· ·
3607' GL		
12. Check Appropriate Bo	x to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO	D: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND AB		
TEMPORARILY ABANDON CHANGE PLAN	_	_
PULL OR ALTER CASING MULTIPLE CO	MPL ☐ CASING/CEMEN	ΓJOB □
DOWNHOLE COMMINGLE ☐ CLOSED-LOOP SYSTEM ☐		
	□ OTHER:	TA 🔽
OTHER: 13. Describe proposed or completed operations.	OTHER: (Clearly state all pertinent details, and	<u> </u>
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODU	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of stranged date in the stran
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODU	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of stranged from the stranged from
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE C	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X +
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODU	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X +
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE C	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X +
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached.	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODU BY THE DETAILS AND THE	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X +
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached. Spud Date: 3/3/2022	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODU BY THE DETAILS AND THE	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X +
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached. Spud Date: 3/3/2022 I hereby certify that the information above is true and	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE DETAILS Rig Release Date: 3/18/2022	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 ls to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X 1 e and belief.
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached. Spud Date: 3/3/2022 I hereby certify that the information above is true and SIGNATURE Roni Mathew	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE CRIST Regulatory Advisor TITLE Regulatory Advisor	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE:
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached. Spud Date: 3/3/2022 I hereby certify that the information above is true and SIGNATURE Roni Mathew Type or print name Roni Mathew	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE DETAILS Rig Release Date: 3/18/2022	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X + The properties of the pr
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached. Spud Date: 3/3/2022 I hereby certify that the information above is true and SIGNATURE Roni Mathew	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE CRIST Regulatory Advisor TITLE Regulatory Advisor	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION of TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE:
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. Please see performed procedure attached. Spud Date: 3/3/2022 I hereby certify that the information above is true and SIGNATURE Roni Mathew Type or print name Roni Mathew	Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cor Approval Well need to PRODUBY THE CRIST Regulatory Advisor TITLE Regulatory Advisor	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of FINAL TA STATUS- EXTENSION OF TA EXPIRES: 11/2/27 Is to be PLUGGED OR RETURNED JCTION DATE STATED ABOVE: X + e and belief. DATE 4/6/2022 DXY.com PHONE: 713.215.7827

SHU 235 API #: 30-025-31423

Temp Abandon – Procedure Performed

- 3/3/22 RUPU, function test BOPE, casing had 950 psi, tbg had 350 psi, bled off gas off of tbg, pressured test tbg to 1000 psi held good, pumped 70 bbls down casing at .75 bpm at 800 psi, no communication into tbg, well stayed w 600 psi, bled off casing into pit, pumped 70 more bbls down casing at .75 bpm well stayed w 300 psi. SION.
- 3/4/22 tbg had 80 psi, csg had 0 psi, NDWH, NUBOP, realesed TAC, pipe was stuck, RUPS, worked stuck pipe, no luck, RDPS, pumped GYP converter, flushed it w 66 bbls, Rih w 2" fishing too, 21 1" rods, to latch on to rods, latched on to fish, worked stuck rod pump, no luck, fishing tool gave up, lost fishing tool sleeve in hole, pooh laying down 21 1" rods, SION.
- 3/5/22 well had 0 psi, RU acid crew, pumped 500 gals of 15% HCL acid, flushed it w 70 bbls of fresh wate, .8 bpm @ 900 psi, rigged down acid crew, RUPS, worked stuck pipe w power swivel bt had no luck, RDPS, SION.
- 3/7/22 tbg had 300 psi, casing had 900 psi, bled off tbg, RUPS, worked stuck tbg w power swivel, pumping down csg at 1 bpm @ 900 psi, no luck, RDPS, Rih w 2 ¼" mill, picked up 23 1" rods, milled on 2" sleeve from previous fishing tool, that stayed on top of 1" coupling, pooh w rods & 2 ¼" mill, Rih w 2" left hand grapple fishing tool to attempt to back off rods, attempt to latch on to rods, had no luck, fishing tool kept slipping, pooh w rods & fishing tool, SION.
- 3/8/22 Rih w 2" fishing tool, attempt to latch on to fish bt had no luck, pooh w fishing tool and noticed we had spring & half of the sleeve we had lost on previous fishing attempt, Rih w another 2" fishing tool, latched on to fish, we then noticed we didn't have pump stroke no more and no stretch on rods, seems like we r stuck up high (550"), think the other piece of sleeve its what gots us stuck, worked rods for the rest of day till fishing tool started slipping off.
- 3/9/22 tbg had 150 psi, csg had 900 psi, bled off psi from tbg, pumped 80 bbls down csg at 1.8 bpm @ 750 psi, RUPS, continued working tbg, for about 4 hrs, noticed less grip on brake handle, inspected brake drum, noticed welds on brake pads were coming apart, using disc brake safetly RDPS, mechanic changed out brake pads, pumped 110 gals of GYP Converter mixed w 5 bbls of fresh water, displaced it w 70 bbls of fresh water, SION.
- 3/10/22 tbg had 100 psi, csg had 900 psi, RU acid crew, pumped 1500 gals of 15% acid down csg @ 2.2 bpm @ 800 psi, displaced w 65 bbls of FW, well went on strong vacuum, RUPS, continued working tbg, tbg started turning free, worked tbg up hole 7 ft, RDPS, SION.
- 3/11/22 tbg had 0 psi, csg had 900 psi, flowed back casing into reverse pit, pumped 80 bbls down csg @ 2.5 bpm @ 500 psi, continued working tbg w PS, finally tbg jumped free, pooh w 18 2 7/8" jts to rods, latched on to 1" rods and worked stuck rod pump, pump came free, pooh laying down 96 1" rods, 53 7/8" bare, 44 7/8" guided rods, rod pump, circulated well w 120 bbls, pooh w total of 36 2 7/8" jts, SION.
- 3/12/22 tbg had 550 psi, csg had 900 psi, killed well, continued pooh w BHA, total of 122 2 7/8" jts, 5.5 TAC, 8 2 3/8" jts, w tbg collar on bottom, pin facing up, left in hole, 26 2 3/8" jts, sn, perf sub, 1 2/3" jt w bull plug, Rih w 2" spear, x-over, 10 2 3/8" L-80 jts, 3 3/4" bumper sub, 3 3/4" jars, 90 2 7/8" L-80 jts, SION.
- 3/14/22 tbg had 1100 psi, csg had 1100 psi, killed well, continued picking up 2 7/8" L-80 tbg, latched on to fish inside 4" liner at 4156', pulled up on fish, started pulling weight at 4138', started working stuck tbg w jars, worked it up to 4130', something came free, cant tell if spear gave out or if tbg came free, SION.
- 3/15/22 tbg had 900 psi, csg had 900 psi, killed well, pooh w 114 2 7/8" L-80 jts, 3 ¾" jars, 3 ¾" bumper sub, x-over, 10 2 3/8" L-80 jts, 2" spear, noticed grapple was broke, Rih w 14 2 3/8" jts w 2 3/8" tbg collar on bottom, x-over, 112 2 7/8" jts, tagged top of fish at 4113", screw into fish, RUWL, and free point tbg, tbg stuck at 4850", cut 2 3/8" tbg at 4802", RDWL, pooh w 112 2 7/8" jts, 14 2 3/8" L-80 jts,recovered 22 2 3/8" jts and 15" of 23rd jt, Rih w 3 ¼" bit, bit sub, 27 2 3/8" jts, x-over, 114 2 7/8" jts down to 4600", pooh above liner top, SION.
- 3/16/22 well had 900 psi, killed well, pooh w 80 2 7/8" jts, 27 2 3/8" jts, w 3 1/4" bit, RUWL, Rih w 4" CIBP, set it at 4541', dump bailed 35' of cmt, TOC 4506', RDWL, Rih w 132 jts, circulated well w 105 bbls of 10# pkr fluid, pressured test well to 500 psi held good, pooh laying down 42 2 7/8" jts, SION.
- 3/17/22 well had 0 psi, finished laying down 2 7/8" L-80 WS tbg 114 jts, Rih w 114 2 7/8" production jts, Midwest swapped out trailers, layed down 2 7/8" production tbg, ran 30 2 3/8" jts and layed them down on float, NDBOP, NU cap flange, ran MIT held good, SION.

Wellbore Diagram



District 1 1625 N French Dr. Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 391-0720

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office


OXV Review and Property Name				₩ 30-0	925-31423	
. Sou	th Hobbs		7110000		235	Tell NO.
		² Surface I	Location			
Company of the second s	Township Range	Feet f	from N/S Line	Feet From	EAV Line	Lea
		Well S	tatus			
YES TA'D WELL NO	SHUT-IN YES	NO INJ	TOR SWD OIL	PRODUCER GAS	2_	DATE 18-22
		wey				
		OBSERVE	ED DATA			
	(A)Surface	(B)Interm(1)	(Cilnterm(2)	(D)Prod	Csng	(E)Tubing
ressure	(A)Surface		(Cilnterni(2)	(D)Prod	Csug	
		(Bilinterin(1)	(Culaterm(2)	(D)Prod	Csng	(E)Tubing
			(Cilaterni(2)	2	7	C02 _
low Characteristics	8	N/A		, e	Csug	CO2 WTR
low Characteristics Puff	& Y/N	N/P	Y//3	e	Y (0)	CO2 WTR GAS
low Characteristics Puff Steady Flow	Y (B) Y (B) Y (B)	N/A Y/N //N	Y// } Y//		y (3)	CO2 WTR
Steady Flow Surges	Y (B)	// P	Y / Y Y / Y Y / Y		Y (5) Y (8) Y (8)	CO2 WTR GAS Type of Field

3-18-22 Cesu Branes

Released to Imaging: 5/31/2022 8:10:37 AM

Signature:	(X	OIL CONSERVATION DIVISION
Printed name.		Entered into RBDMS
Title:		Re-test CR
E-mail Address:		
Date;	Phone:	
	Witness:	

Received by OCD: 4/21/2022 7:31:42 AM



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 100444

COMMENTS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	100444
	Action Type:
	[C-103] Sub. Temporary Abandonment (C-103U)

COMMENTS

(Created By		Comment Date
	plmartinez	DATA ENTRY PM	5/31/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 100444

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	100444
	Action Type:
	[C-103] Sub. Temporary Abandonment (C-103U)

CONDITIONS

Created By		Condition Date
kfortner	None	5/26/2022