

Rudy Wildenstein

From: Cordero, Gilbert, EMNRD <Gilbert.Cordero@state.nm.us>
Sent: Thursday, July 07, 2022 9:42 AM
To: Rudy Wildenstein
Subject: FW: [EXTERNAL] missing Sundries

Gilbert Cordero
NMOCD NM South
Staff Manager
C 575-626-0830

From: Amos, James A <jamos@blm.gov>
Sent: Wednesday, July 6, 2022 3:44 PM
To: Cordero, Gilbert, EMNRD <Gilbert.Cordero@state.nm.us>
Subject: Fw: [EXTERNAL] missing Sundries

Gilbert,

As per our conversation this morning the wells have been plugged. I Accepted them for Record on 7/5/22, went to print the Reports and they are all gone. We're working to retrieve them, but can't find them. I have been trying to reenter the reports only to have the program acting up. We will get this resolved, just not sure how long it will take. Thanks

Accepted for record – NMOCD gc 7/7/2022

From: Rudy Wildenstein <RWildenstein@silverbackexp.com>
Sent: Wednesday, July 6, 2022 3:09 PM
To: Amos, James A <jamos@blm.gov>
Cc: Gilbert Cordero (gilbert.cordero@state.nm.us) <gilbert.cordero@state.nm.us>
Subject: [EXTERNAL] missing Sundries

This email has been received from outside of DOI - Use caution before clicking on links, opening attachments, or responding.

Mr. Amos,
Could you forward this email to Gilbert Cordero with your verification that these Sundries were accepted and are lost in the system.
Thanks very much

Well Name	API	BLM Sub Report Sundry II	OCD Subseq Submission Date	OCD Sunseq Submission Action II
Federal BW #10	30-015-23603	2665020	7/5/2022	122800
Federal BW #2	30-015-20455	2665019	7/5/2022	122807
Federal BZ #13	30-015-21832	2669749	7/5/2022	122809
Federal BZ #14	30-015-21856	2670590	7/5/2022	122813
Federales BO #4	30-015-20474	2669751	7/5/2022	122816
Federales BO #5	30-015-21153	2670296	7/5/2022	12756

Rudy Wildenstein
 Engineering Advisor
 Silverback Exploration II
 19707 IH-10 W
 Suite 201
 San Antonio, TX 78257
rwildenstein@silverbackexp.com
 C 713-829-0362

Actual P&A Procedure

Well: Federal BW #2
API: 300152404500S1
Location: 22-17S-25E

Date	Activity
5/2/2022	NU BOP. Run bit and scraper to 1350'. POH. Secure well SDFN.
5/3/2022	Set CIBP at 1312'. Pressured up on csg, did not hold pressure. Secure well SDFN.
5/4/2022	Set 50 sx CI C cmt, WO cmt 4 hrs. Tag top of plug at 1182'. Pressure test csg to 350 psi, witnessed by BLM. Pump 60 sx CI C plug from 845' to surface. ND BOP, flange up wellhead with 4' sub, pump 10 bbls cmt, circulate to surface. RD and release workover unit.
5/9/2022	Cut casing 3' below GL. Install dry hole marker.

Well P&A

Federal BW #2 as Plugged					Sec-TWN-RNG: 22-17S-25E		30-015-20455		
					Footage Calls: 330' FSL & 1650' FEL		Elev 3521' GR		
COMMENTS									
CMT PLUG 845'-SURFACE.	<div><div>A</div><div>B</div><div>C</div></div>								
Top San Andres at 747'									
CMT PLUG 1312'-1182'.	<div><div>A</div><div>B</div><div>C</div></div>								
Perforations at 1358'-1457'									
PBTD: MD									
TD: 1,475 MD									

CASING DETAIL									
#	HOLE	CSG	WGHT	GRADE	Top	Depth	TOC	SX	
A	13 3/4	10.75	32	J-55	0	206	Circ	80	
B	8 7/8	7	20, 23	J-55	0	1,151	Circ	325	
C	6 1/8	5.5	14	J-55	0	929	Circ		
C	6 1/8	4.5	9.5	J-55	929	1,475	Circ	125	
FORMATION TOPS									
FORMATION		TOP		FORMATION				TOP	
SAN ANDRES		747'							
TUBING DETAIL									
OD		GRADE		WGHT		TOP		BASE	
2 3/8						0		1288'	
PERFORATION DETAIL									
	FORMATION		TOP		BASE		TREATMENT		
A	SAN ANDRES		1358'		1457'		6500 GAL 15% ACID, 400,000# 20/40, 8000 GAL WATER		
PLUGS									
#	sx	Class	Top	Bottom	Ht	Notes		Tag	
1	50	C	1182	1312	130	CIBP + cmt plug		Y	
2	60	C	0	845	845	cmt plug			

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 123370

CONDITIONS

Operator: Silverback Operating II, LLC IH10 West, Suite 201 San Antonio, TX 78257	OGRID: 330968
	Action Number: 123370
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
jagarcia	This well was plugged in violation of 19.15.25.9 NMAC, as the well was plugged without a required Division approved notice of intention sundry. Because this is a federal well the filing is required pursuant to 19.15.7.11 NMAC which requires "For wells located on land that the United States or a native American nation, tribe or pueblo owns, an operator shall file applications for permit to drill, deepen or plug back, BLM form no. 3160-3; sundry notices and reports on wells, BLM form no. 3160-5; and well completion or recompletion report and log, BLM form no. 3160-4 with the BLM in lieu of filing the corresponding division forms with the division. All such forms are, however, subject to division approval in the same manner and to the same extent as the corresponding division forms."	7/7/2022