
| Submit 1 Copy To Appropriate District | State of New Mexico | Form C-103 | | |
|---|--|--|--|--|
| Office District 1 – (575) 393-6161 | Energy, Minerals and Natural Resources | Revised July 18, 2013 | | |
| 1625 N. French Dr., Hobbs, NM 88240 | - | WELL API NO. 30-25-26356 | | |
| <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 | OIL CONSERVATION DIVISION | 5. Indicate Type of Lease | | |
| District III - (505) 334-6178 | 1220 South St. Francis Dr. | STATE FEE | | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. | | |
| 1220 S. St. Francis Dr., Santa Fe, NM | | | | |
| 87505 | TICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name | | |
| (DO NOT USE THIS FORM FOR PROPO | OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A | The Board I cannot be a series of the series | | |
| DIFFERENT RESERVOIR. USE "APPL | ICATION FOR PERMIT" (FORM C-101) FOR SUCH | Bobbi State Waterflood Unit | | |
| PROPOSALS.) 1. Type of Well: Oil Well | Gas Well Other WSW | 8. Well Number 10 | | |
| | Gus Well Gullet We W | 9. OGRID Number | | |
| 2. Name of Operator SUNDOWN ENERGY LP | | 232611 | | |
| 3. Address of Operator | | 10. Pool name or Wildcat | | |
| 16400 DALLAS PARKWAY, ST | E. 100 DALLAS, TX 75248 | WSW; Delaware | | |
| 4. Well Location | | | | |
| | 1980 feet from the SOUTH line and | 1930 feet from the <u>EAST</u> line | | |
| Section 20 | Township 18S Range 36E | NMPM LEA County | | |
| Missand Sylve Is a factor | 11. Elevation (Show whether DR, RKB, RT, GR, | etc.) | | |
| | 3847' GR | | | |
| | | | | |
| 12. Check | Appropriate Box to Indicate Nature of Not | ice, Report or Other Data | | |
| NOTICE OF I | NTENTION TO: | UBSEQUENT REPORT OF: | | |
| PERFORM REMEDIAL WORK | | | | |
| TEMPORARILY ABANDON | | DRILLING OPNS. □ PAND A 🛛 | | |
| PULL OR ALTER CASING | | MENT JOB | | |
| DOWNHOLE COMMINGLE | | | | |
| CLOSED-LOOP SYSTEM |] | | | |
| OTHER: | pleted operations. (Clearly state all pertinent detail | not convert to inj. | | |
| of starting any proposed v | vork). SEE RULE 19.15.7.14 NMAC. For Multiple | e Completions: Attach wellbore diagram of | | |
| proposed completion or re | ecompletion. | | | |
| | | ** | | |
| SEE ATTACHED SUBSEC | LUENT PLUGGING REPORT AND FINAL WELL SK | ETCH. | | |
| | | - | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Spud Date: | Rig Release Date: | e | | |
| , | | | | |
| | | | | |
| I hereby certify that the information | n above is true and complete to the best of my know | rledge and belief. | | |
| | | | | |
| SIGNATURE More | TITLE Joint Ops Engineer | DATE6/22/2023 | | |
| Type or print name Steve Flynn E-mail address: sflynn@sundownenergy.com PHONE 214-368-6100 Ext 2114 | | | | |
| For State Use Only | | | | |
| | TITLE Petroleum Spec | cialist DATE 07/5/2023 | | |
| APPROVED BY: Conditions of Approval (if any): | TITLE Petroleum Spec | DA11 0110/2020 | | |
| Conditions of Whitean (it and). | | | | |


C-103 Subsequent Report – BOBBI STATE WFU #10

SPOKE W/ KEY W/ NMOCD, GOT APPROVAL TO MOVE UP PLUG DUE TO PERFS @ 6,432'. ALSO RECEIVED APPROVAL FROM KERRY TO OMIT PERF & SQZ ON PLUGS #5, #6 & #7 AS LONG AS WE HAD A CBL THAT SHOWED CEMENT BEHIND PIPE AT THOSE DEPTHS. TIH W/ 5-1/2" CIBP & SET @ 6,350'. CIRC HOLE W/ MUD & TEST CSG TO 500# - HELD GOOD. MIX & SPOT A 25 SX CLASS C CMT PLUG @ 6350'. RIH & TAGGED TOC @ 6,102' -- OK PER KERRY FORTNER W/ OCD. HE ALSO INDICATED THERE WAS NO NEED TO TAG PLUG @ 5,530' BUT WILL NEED TO TAG PERF & SQZ PLUG @ 4,386'. RU RENEGADE WL TO RUN CBL FROM 6,100' -- 0' -- FOUND CMT @ 4,480' AND VERY LITTLE CMT ELSEWHERE. EMAILED CBL TO KERRY W/ OCD -- INSTRUCTED US TO PERF & SQZ PLUGS @ 3,800', 3,230', 1,926', 330' & 100' & CIRC CMT TO SURF. RIH TO 5,530' AND SPOTTED A 35 SXS CMT PLUG @ 5530'. POOH AND RU RENEGADE WL, RIH & PERF @ 4,386'. POOH & RD WL. HOOK ONTO CSG & ATTEMPTED TO EST INJ RATE TO NO AVAIL -- PRESS UP TO 600# PSI & HELD. SPOKE W/ KERRY W/ OCD -- OK'D TO DROP DOWN TO 4,436', SPOT 25 SXS CMT, WOC & TAG. RIH OPEN ENDED TO 4,436' & SPOTTED A 25 SXS CMT PLUG @ 4436'. TAGGED TOC @ 4,240' -- OK PER KERRY W/ OCD VIA TEXT. ALSO LET HIM KNOW THAT WE WOULD BE PERFORATING & ATTEMPTING TO EST RATE. POOH & LD TBG TO 1,981'. RU RENEGADE WL, RIH THROUGH TBG GUN AND PERF @ 3,800'. POOH. HOOKED ONTO TBG AND ATTEMPTED TO EST RATE TO NO AVAIL -- PRESS UP TO 600# PSI & HELD. SPOKE W/ KERRY W/ OCD -- INSTRUCTED US TO SPOT 25 SXS CMT @ 3,850', WOC & TAG. RIH TO 3,850' & SPOTTED 25 SXS CMT @ 3850'. POOH W/ 30 STANDS & WOC. RIH & TAGGED TOC @ 3.608'. POOH TO 1,981'. RU RENEGADE WL, RIH THROUGH TBG GUN & PERF @ 3,230'. POOH & RD WL. HOOKED ONTO TBG & ATTEMPTED TO EST INJ RATE TO NO AVAIL -- PRESSURE UP TO 600# PSI & HELD. SPOKE W/ KERRY W/ OCD -- INSTRUCTED US TO SPOT 25 SXS CMT @ 3,280', WOC & TAG. RELEASED PRESS. RIH OPEN ENDED TO 3,280' & SPOTTED A 25 SXS CMT PLUG @ 3280'. TAGGED TOC @ 3,010' -- OK PER KERRY W/ NMOCD. POOH & LD TBG TO 1,100'. RU RENEGADE WL, RIH THROUGH TBG & PERF @ 1,926'. POOH & RD WL. HOOKED ONTO TBG & ATTEMPTED TO EST INJ RATE TO NO AVAIL -- PRESS UP TO 600# PSI & HELD. SPOKE W/ KERRY W/ OCD --INSTRUCTED US TO DROP 50' BELOW PERFS & SPOT 30 SXS CMT. RELEASED PRESS. RIH OPEN ENDED TO 1,976' AND SPOTTED A 25 SXS CMT PLUG 1976'. POOH. RU WL, RIH & PERF @ 330'. POOH & RD WL. RIH OPEN ENDED & TAGGED TOC @ 1,710' -- OK PER KERRY. HE ALSO OK'D TO CIRC CMT TO SURF FROM 330' IF WE COULD GET GOOD CIRC. IF NOT, WE ARE TO SQZ 30 SXS CMT, WOC & TAG. POOH & LD TBG. PU 5-1/2" PKR & SET @ 30'. HOOKED ONTO TBG & EST INJ RATE @ 1 BPM @ 500# PSI. MIX & SQZ 30 SXS CMT @ 330' & WOC W/ 100# SIP. CWI & WOC 4 HRS. OPEN WELL, UNSET PKR & LD. RIH OPEN ENDED & TAGGED TOC @ 183'. POOH & LD TBG. RU RENEGADE WL, RIH & PERF @ 100'. POOH & RD WL. HOOKED ONTO 5-1/2" & BROKE CIRC AROUND 8-5/8" ANNULUS -- GOOD CIRC. CLOSED 8-5/8" VALVE & ATTEMPTED TO GET CIRC AROUND 13-3/8" ANNULUS TO NO AVAIL -- PRESS UP TO 500# PSI & HELD. RD FLOOR & ND BOP. FLANGED UP WH & CIRC 35 SXS CMT AROUND 8-5/8" ANNULUS. TAKE OFF FLANGE & FOUND CMT @ 2'. RD UNIT & DIG OUT CELLAR & ANCHORS 4' BELOW GROUND LEVEL. CUT OFF WELLHEAD, VERIFY CEMENT AT SURF. WELD ON PLATE AND INSTALL DRY HOLE MARKER. BACKFILL CELLAR AND ANCHOR HOLES. CLEAN LOCATION & RD ALL EQUIPMENT. WELL COMPLETE 6/13/23. WELL PLUGGED & ABANDONED.

WELL DATA SHEET



WELL DATA SHEET



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 231611

CONDITIONS

| Operator: | OGRID: |
|-------------------|--------------------------------|
| SUNDOWN ENERGY LP | 232611 |
| 16400 Dallas Pkwy | Action Number: |
| Dallas, TX 75248 | 231611 |
| | Action Type: |
| | [C-103] Sub. Plugging (C-103P) |

CONDITIONS

| Created By | | Condition Date |
|---------------|---------------------------|-------------------|
| john.harrison | None - Well P&A'd 6/22/23 | 7/5/2023 |