Form 3160-5 (June 2019)

# UNITED STATES DEPARTMENT OF THE INTERIOR

F	ORM A	PPROVED
C	MB No.	1004-0137
Exp	ires: Oc	tober 31, 20

5. Lease Serial No. **BUREAU OF LAND MANAGEMENT** NMNM0413245 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 BLACK RIVER FED '10' COM/NMNM94519 1. Type of Well 8. Well Name and No. ✓ Gas Well Other BLACKRIVER 10 FEDERAL COM/2 Oil Well 9. API Well No. 3001532634 2. Name of Operator CIMAREX ENERGY COMPANY OF COLORADO 3a. Address 6001 DEAUVILLE BLVD STE 300N, MIDLAND, 7 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area S CARLSBAD/S CARLSBAD (432) 620-1936 11. Country or Parish, State 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) EDDY/NM SEC 10/T24S/R26E/NMP 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Production (Start/Resume) Deepen Acidize Notice of Intent Well Integrity Reclamation Hydraulic Fracturing Alter Casing Other Recomplete New Construction Casing Repair Subsequent Report Temporarily Abandon ✓ Plug and Abandon Change Plans Water Disposal Plug Back Convert to Injection Final Abandonment Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) 1) SET 5-1/2" CIBP @ 11,100'; CIRC. WELL W/ M.L.F.; PRES. TEST 5-1/2" CSG. TO 500# X HOLD FOR 30 MINS; RUN CBL. 2) PUMP (30) SXS. CLASS "H" CMT. @ 11,100'-9,900' (T/MRRW.); WOC X TAG TOC. 3) PUMP (25) SXS. CLASS "H" CMT. @ 8,553'-8,373' (T/WLCP.). 4) PUMP (25) SXS. CLASS "C" CMT. @ 7,075'-6,915' (5-1/2" DV TOOL); WOC X TAG TOC. 5) PERF. X ATTEMPT TO SQZ. (60) SXS. CLASS "C" CMT. @ 5,339'-5,189' (T/BNSG.); 6) PERF. X ATTEMPT TO SQZ. (60) SXS. CLASS "C" CMT. @ 3,268'-3,138' (9-5/8" CSG.SHOE); WOC X TAG TOC. 7) PERF. X ATTEMPT TO SQZ. (50) SXS. CLASS "C" CMT. @ 1,932'-1,822' (T/DLWR.). 8) PERF. X ATTEMPT TO SQZ. (50) SXS. CLASS "C" CMT. @ 1,535'-1,425' (B/SALT); WOC X TAG TOC. 9) PERF. X ATTEMPT TO SQZ. (100) SXS. CLASS "C" CMT. @ 649'-390' (T/SALT, 9-5/8" CSG.SHOE); WOC X TAG TOC. 10) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, (25) SXS. CLASS "C" CMT. @ 63'-3'. 11) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. ON ALL ANNULI; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE A CLOSED-LOOP SYSTEM WITH A STEEL TANK AND HAUL CONTENTS TO THE

REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)					
DAVID EYLER / Ph: (432) 687-3033	Agent /2/26/2024				
Signature (Electronic Submission)	Date 11/01/	2024			
THE SPACE FOR FEDERAL OR STATE OFICE USE					
Approved by	ENGINEER	12/24/2024			
KEITH P IMMATTY / Ph: (575) 988-4722 / Approved	Title	Date			
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject least which would entitle the applicant to conduct operations thereon.	Office CARLSBAD				
The toxic C.C. it 1001 1 Title 42 H.C. C. Cartier 1212 make it a grime for any	person knowingly and willfully to make to any	department or agency of the United States			

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

# **Additional Information**

## **Location of Well**

 $0. \ SHL: \ SESW \ / \ 1160 \ FSL \ / \ 1400 \ FWL \ / \ TWSP: \ 24S \ / \ RANGE: \ 26E \ / \ SECTION: \ 10 \ / \ LAT: \ 32.228157 \ / \ LONG: \ -104.2850189 \ (\ TVD: \ 0 \ feet \ )$  BHL:  $\ SESW \ / \ 1160 \ FSL \ / \ 1400 \ FWL \ / \ TWSP: \ 24S \ / \ SECTION: \ / \ LAT: \ 0.0 \ / \ LONG: \ 0.0 \ (\ TVD: \ 0 \ feet \ )$ 


(Form 3160-5, page 3)

- 1) SET 5-1/2" CIBP @ 11,072' ADJUSTED TO BE MIN 50' FROM PERFS; CIRC. WELL W/ M.L.F.; PRES. TEST 5-1/2" CSG. TO 500# X HOLD FOR 30 MINS; RUN CBL.
- 2) PUMP (30) SXS. CLASS "H" CMT. @ 11,072'-9,900' (T/MRRW.); WOC X TAG TOC.
- 3) PUMP (25) SXS. CLASS "H" CMT. @ 8,553'-8,328' (T/WLCP.).
- 4) PUMP (25) SXS. CLASS "C" CMT. @ 7,075'-6,875' (5-1/2" DV TOOL); WOC X TAG TOC.
- 5) PERF. X ATTEMPT TO SQZ. (60) SXS. CLASS "C" CMT. @ 5,339'-5,161' (T/BNSG.);
- 6) PERF. X ATTEMPT TO SQZ. (60) SXS. CLASS "C" CMT. @ 3,268'-3,120' (9-5/8" CSG.SHOE); WOC X TAG TOC.
- 7) PERF. X ATTEMPT TO SQZ. (50) SXS. CLASS "C" CMT. @ 1,932'-1,808' (T/DLWR.).
- 8) PERF. X ATTEMPT TO SQZ. (50) SXS. CLASS "C" CMT. @ 1,535'-1,425' (B/SALT); WOC X TAG TOC.
- 9) PERF. X ATTEMPT TO SQZ. (155) SXS. CLASS "C" CMT. @ 649'-SURFACE' (T/SALT, 9-5/8" CSG.SHOE); WOC X TAG TOC. 500' SURFACE PLUG NEEDED DUE TO CRITICAL CAVE KARST AREA. COMBINED SALT, SHOE AND SURFACE PLUGS
- 10) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, (25) SXS. CLASS "C" CMT. @ 63'-3'.
- 11) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. ON ALL ANNULI; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.


DURING THIS PROCEDURE WE PLAN TO USE A CLOSED-LOOP SYSTEM WITH A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

BLM NOTE: DEPTHS ADJUSTED TO HAVE 10% EXCESS PER 1000'.

KEITH IMMATTY Digitally signed by KEITH IMMATTY Date: 2024.12.23 20:54:07 -07'00'



Printed 10/30/2024



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 415287

## **CONDITIONS**

Operator:	OGRID:
CIMAREX ENERGY CO. OF COLORADO	162683
6001 Deauville Blvd	Action Number:
Midland, TX 79706	415287
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

## CONDITIONS

Created By	Condition	Condition Date
gcordero	Adhere to current Plug & Abandon (P&A) Conditions Of Approvals (COA).	1/3/2025
gcordero	A Cement Bond Log (CBL) is required to be submitted to electronic permitting.	1/3/2025
gcordero	Submit Cement Bond Logs (CBL) prior to submittal of C-103P.	1/3/2025