

**State Of New Mexico**  
**Energy, Minerals and Natural Resources Department**

12-Feb-25

**HILCORP ENERGY COMPANY**

1111 Travis Street  
Houston, TX 77002

**Pre Enforcement Notification**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

**INSPECTION DETAIL SECTION**

[30-045-32935] NEGRO CANYON #102S      OGRID: 372171      A-02-31N-08W 1320 FNL 190 FEL

| Inspection Date | Type Inspection                                                          | Inspector             | Inspection No. |
|-----------------|--------------------------------------------------------------------------|-----------------------|----------------|
| 2/12/2025       | Routine Inspection                                                       | [CZS] Clarence Smith  | iCZS254344875  |
| Violation       | Title                                                                    | Corrective Action Due |                |
| cCZS254361014   | 19.15.29 Releases Surface Leaks/Spills                                   | 5/13/2025             |                |
|                 | <i>(Staining around well head white crust needs to be cleaned up. )</i>  |                       |                |
| cCZS254361015   | 19.15.29 Releases Surface Leaks/Spills                                   | 5/13/2025             |                |
|                 | <i>(Staining around pump jack skid motor side needs cleaned up. )</i>    |                       |                |
| cCZS254361016   | 19.15.29 Releases Surface Leaks/Spills                                   | 5/13/2025             |                |
|                 | <i>(Staining inside berm next to production tanks needs cleaned up.)</i> |                       |                |

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.