

ceined by Opp Po Appropriate bistrict 9	PM State of New Mexico	Form C-103 ¹ of
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		30-025-36629
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		
	CICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
`	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Roueche 5
PROPOSALS.)	Cas Wall Other	8. Well Number 001
Type of Well: Oil Well X Name of Operator	Gas Well Other	9. OGRID Number
Armstron	g Energy Corporation	1092
3. Address of Operator		10. Pool name or Wildcat
	1973, Roswell NM 88202	Humble City; Wolfcamp
4. Well Location		
Unit Letter P :	feet from the South line and	
Section 5	Township 17S Range 37E	NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT, GR, 3790' GR	etc.)
	3/90 GR	
12 Check	Appropriate Box to Indicate Nature of Noti	ce Report or Other Data
12. Check	Appropriate Box to indicate ivalure of ivon	ce, Report of Other Data
NOTICE OF I	NTENTION TO:	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	-	_
TEMPORARILY ABANDON X	· —	DRILLING OPNS. P AND A
PULL OR ALTER CASING		IENT JOB
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM		
CLOSED-LOOP SYSTEM OTHER:	□ OTHER:	П
	pleted operations. (Clearly state all pertinent details	, and give pertinent dates, including estimated date
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple	Completions: Attach wellbore diagram of
proposed completion or re	completion.	
Armstrong Ener	gy Proposes the following work plan to temporarily	abandon the Roueche 5 #1:
1. RUPU,	TOOH w/ tbg	
	BP @ 6200' w/ 35' cement	
	tbg, circ w/ 2% KCL	
4. Test cs	g to 500 psi for 30 min w/ chart	
Spud Date:	Rig Release Date:	
~pua 2 a.c.	Ing resease 2 me.	
I hereby certify that the information	a above is true and complete to the best of my knowl	edge and belief.
,	1	
CICNATIVE O		2/2/2025
SIGNATURE Jeffery 7	TITLE Operations En	ngineerDATE3/3/2025
Type or print name <u>Jeffery Te</u>	ew E-mail address: jtew@aeo	cnm.com PHONE: <u>575-625-2222</u>
For State Use Only	2 mai address	
-		
APPROVED BY:	TITLE	DATE
Conditions of Approval (if any):		









Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 438656

CONDITIONS

Operator:	OGRID:
ARMSTRONG ENERGY CORP	1092
P.O. Box 1973	Action Number:
Roswell, NM 88202	438656
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
gcordero	When ready to T&A must drill out plugs and cement across BS @ 8470'	4/4/2025
gcordero	Must submit casing integrity log prior to subsequent approval.	4/4/2025
gcordero	Must submit development plan for well with details and timelines.	4/4/2025
gcordero	Passing MIT test in accordance with 19.15.26.11 or 19.15.25.12-14 NMAC will be required at time of work.	4/4/2025
gcordero	Notify the OCD inspection supervisor via email 24 hours prior to beginning Temporarily Abandonment (TA) operations.	4/4/2025