

Santa Fe Main Office
Phone: (505) 476-3441
General Information
Phone: (505) 629-6116

Online Phone Directory Visit:
<http://www.emnrd.nm.gov/oed/contact-us/>

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

WELL API NO.
30-15-03161
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-7596
7. Lease Name or Unit Agreement Name Robinson St
8. Well Number 5
9. OGRID Number 371484
10. Pool name or Wildcat GRBG Jackson Q G SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Rover Operating	
3. Address of Operator 318 Adams St, 10 th Floor Chicago, IL 60606	
4. Well Location Unit Letter D : 330 feet from the N line and 330 feet from the W line Section 27 Township 175 Range 29E NMPM County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3544	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING MULTIPLE COMPL
DOWNHOLE COMMINGLE
CLOSED-LOOP SYSTEM
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. P AND A
CASING/CEMENT JOB
OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Notify NM Regulatory 24 prior

1.9/8- MIRU; 2. 9/9-POOH WITH PRODUCTION EQUIPMENT, SET 5 1/2 CIBP 2775, TIH WITH TBG, SISD; 3.9/10-SPOT 13SX ON CIBP WOC, & TAG 2580, LOAD HOLE PRESSURE TO 500PSI 10MIN, 0 PRESS, SET CIBP 2483, TIH WITH PKR NO TEST, SISD; 4. 9/11-SPOT 25 SX ON CIBP WOC & TAG 2260', PRESS TO 500 PSI, HOLD 30MIN, RUN CBL SISD; 5. 9/12-PERF 1748 SQZ 30SX WOC 4HRS, NO TAG, SQZ 30SX ISIP 600 PSI S.D.; 6. 9/15- TAG TOC 1810, PERF 1160 SQZ 30SX WOC 4HRS NO TAG SQZ 30SX SISD; 7. 9/16-TAG TOP 1610, PERF 870 SQZ 100 SX WOC 4 HRS TAG 560 PERF 322 SQZ 100SX ISIO 500PSI SD; 8. 9/17-O PSI OPEN AND ND BOPVERIFY CEMENT AT SURF IN AND OUT WELLHEAD CEMENTED TO SURF, CO MAST ANCHORS, CLEAN LOCATION RD ALL P&A EQUIP, S.D. JOB COMPLETE D.H.M. TUBE INSTALLED

P&A MUD BETWEEN ALL PLUGS, CLOSED LOOP ALL FLUIDS TO LICENSED FACILITY

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

CEO

DATE

10/7/2025

Type or print name
For State Use Only

E-mail address:

PHONE:

APPROVED BY: _____ TITLE: _____ DATE: _____
Conditions of Approval (if any):

Robinson #5 Plugging Report

ROBINSON ST.#5

Sept 8, 2025

MIRU Maverick Rig.

Sept 9, 2025

POOH with Production Equipment

Set 5.5 inch CIBP at 2,775 feet

TIH with Tubing

SISD

Sept 10, 2025

Spot 13 Sks on CIBP

WOC and Tag at 2580 ft

Load hole and pressure to 500 psi for 10 min, 0 pressure

Set CIBP @ 2,483 ft

TIH with PKR No test

SISD

Sept 11, 2025

Spot 25 sks on CIBP

WOC and tag @ 2,260 ft

Pressure to 500 psi, Hold 30 Min

Run CBL

SISD

September 12, 2025

Perforate 1,748 ft

Squeeze 30 sks WOC 4 hrs, No tag

Squeeze 30 sks ISIP 600 PSI

SD

September 15 2025

Tag Top Cement @ 1,810

Perf @ 1160

Squeeze 30 sks WOC 4 hrs No Tag

Sqz 30 sks

SISD

September 16, 2025

Tag TOC 1,610

Perf @ 870 ft

SQZ 100 sks WOC 4 hrs

Tag @ 560 ft

Perf @ 322

Squeeze 100 sks ISI 500 psi

SD

September 17, 2025

0 PSI

Open and ND BOP

Verify cement at surface in and out wellhead cemented to surface

Wellhead removed

CO Mast Anchors, clean location Rd, all PA equipment

SD

DHM installed


PA mud between all plugs

Closed Loop

All Fluids to Licensed Facility

Rover Operating, LLC
WELLBORE DIAGRAM

Lease/Well No.	Robinson State #5	ELEVATION, GL: 3544'
Location	330' FNL & 330' FWL D, SEC 27, T17S, R29E EDDY CO, NM	FIELD: GRAYBURG JACKSON;SR-Q-G-SA
LEASE NO	B-7596	Spudded: 2/2/1961
API No.	30-015-03161	Completed: 3/22/1961
		LAT: 32.8119011
		LONG: -104.0701523



Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 546069

CONDITIONS

Operator: ROVER OPERATING, LLC 318 West Adams Street Chicago, IL 60606	OGRID: 371484
	Action Number: 546069
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
gcordero	Clean Location in accordance with 19.15.25.10 NMAC.	1/27/2026
gcordero	Submit C-103Q within one year of plugging.	1/27/2026