Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONCERNATION BUTTOUS		WELL API NO. 30-021-20131
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	i., Aztec, NM 87410 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			West Bravo Dome Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other CO2 Supply			8. Well Number 091G
2. Name of Operator			9. OGRID Number 495
Hess Corporation 3. Address of Operator PO Box 840			10. Pool name or Wildcat (96387)
Seminole TX 79360			West Bravo Dome CO2 Gas
4. Well Location			
Unit Letter G: 1650 feet from the NORTH line and 1650 feet from the EAST line Section 9 Township 19N Range 29E NMPM County HARDING			
Section 9 Township 19N Range 29E NMPM County HARDING 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
5366'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON 🖾 REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
WBDU 1929-091G C-103 NOI to P&A well:			
Per C-103 Subsequent Report dated 10/12/11, this well had a CIBP set at 2700' with 10 sks of cement on top of it in October, 2011. Calculated 96' of cement, TOC at 2604'. Well was approved by NMOCD as TA effective			
10/24/11. Hess now proposes to convert this well from TA to P&A per the procedure below:			
Check pressure on wellhead, excavate around wellhead, cut off wellhead below ground level, spot 3 sks of			
cement in top of casing, weld steel plate across casing and install P&A marker, backfill around P&A marker, cut off anchors below ground level and level/clean location. Reseed location during late summer, 2014.			
The state of the anti-policy ground level and level/clean rocation. Reseed location duffing late stammer, 2014.			
Spud Date: 08/01/2007	Rig Release Da	e:	
\			w C
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Regulatory Specialist DATE 03/04/2014			
Pita C Cm			
Type or print name Rita C. Sm For State Use Only	E-mail address:	rsmith@hess	PHONE: 432-758-6726
APPROVED BY:			