Submit 3 Copies to Appropriate	State of New Mexico Energy, Minerals, and Natural Resources Department			Form C-103 Revised 1-1-89	
District Office	,		•		
DISTRICT <u>I</u>	OIL CONS	ERVATIO	N DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088			30-059-20034	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas I	Lease No.
	NOTICES AND DEC	ODTE ON W	iEl I S		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				the option of the control of the control of the control of the	
				7. Lease Name or U	nit Agreement Name
(FC	DRM C-101) FOR SUCH PROF	POSALS.)			
1. Type of Well	<del></del> -			BRAVO DOME	CO2 GAS UNIT
OIL GAS		OTHER	CO2	}	
2. Name of Operator				8. Well No.	<del></del>
OXY USA Inc.				2232-121G	
3. Address of Operator				9. Pool name or Wildcat	
P.O. Box 303, AMISTA	D, NEW MEXICO	88410		BRAVO DOME	
	TILLY MEXICO			514110 501112	
4. Well Location Unit Letter G ; 198	Feet From The	NORTH	Line and 1980	Feet From The	EAST Line
Section 12	Township	22N	Range 32E	NMPM UNION	County
	10. Eleva	stion (Show whe 5128	ther DF, RKB, RT, GR, etc.) GR		
Chec	k Appropriate Box	to Indicate	Nature of Notice, R	eport, or Other Dat	а
	INTENTION TO:	i to morati		BSEQUENT REPOR	
`		<del></del> -	i	DOCQUENT REPUR	1 OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	L AL	TERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING C	PNS. PL	UG AND ABANDONMENT
PULL OR ALTER CASING			CASING TEST AND CEM	ENT JOB	
			Į.	<u> </u>	<del></del>
OTHER:		<u></u> _	OTHER: Yearly Bradenhe		
12. Describe Proposed or Completed Operatio	ns (Clearly state	all pertinent detai	ls, and give pertinent dates, inclu	ding estimated date of starting	any proposed work)
YEAR MONTH/DAY	TBG. PRESS.	CSG. PR	RESS. BLEED DOW	/N TIME	
1991 9/20	310#	0	COS. BELLD DOW	IN THAIR	
1992 9/17	310#	Ö			
1993 6/8	310#	ő			
1994 7/12	300#	Ö			[
1995					
1996 6/4	310#	0			}
1997 9/4	310#	0			
1998 6/11	310#	0			
1999 7/10	310#	0			
2000 9/12	310#	0			
2001 1/5	310#	0			
2002 6/19	310#	0			
1 1	310#	0			
2003 8/18		-			1
2003 8/18 2004 7/15	310#	0			
2003 8/18		0			
2003 8/18 2004 7/15 2005 8/11	310# 310#	0	· <del></del>		
2003 8/18 2004 7/15 2005 8/11	310# 310#	O pest of my knowled			
2003 8/18 2004 7/15 2005 8/11  Thereby certify that the information above SIGNATURE	310# 310#	0	ge and belief. Well Analyst	DATE	8/15/05
2003 8/18 2004 7/15 2005 8/11  Thereby certify that the information above SIGNATURE  TYPE OR PRINT NAME M. L. CLAY	310# 310#	O pest of my knowled		DATE	
2003 8/18 2004 7/15 2005 8/11  Thereby certify that the information above SIGNATURE	310# 310#	O  est of my knowled  TITLE  .		TELEPH	