Office Appropriate District	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-007-20697-
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	20695
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fc, NM 87505		
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION	FOR PERMIT" (FORM C-101) FOR SUCH	VPR A
PROPOSALS.) 1. Type of Well: Oil Well Gas W	Vell 🛛 Other Coalbed Methane	8. Well Number 249
\ <u></u>	ven 23 Other Coalbed Wethane	
2. Name of Operator	P. D.COMDANIV I D	9. OGRID Number 180514
	& P COMPANY, L.P.	10. Pool name or Wildcat
3. Address of Operator PO BOX 190, RATON, NM 87740		Stubblefield Canyon – Vermejo Gas
\ <u></u>	U, KATON, NW 67/40	Stubblenelu Canyon – verniejo Gas
4. Well Location		
Unit Letter F: 1538	feet from the North line and 13	90 feet from the West line
Section 25 Township	31N Range 19E NMPM	Colfax County
The state of the s	Elevation (Show whether DR, RKB, RT, GR, e	(c.) 建加油和加油的电影中的多次。
8,305' (GL)		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appro	priate Box to Indicate Nature of Notic	e, Report or Other Data
NOTION OF INTENT		DOCOLICKIT OCDODE OC
NOTICE OF INTEN		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLU	IG AND ABANDON 🔲 REMEDIAL WO	ORK ALTERING CASING
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA	IG AND ABANDON ☐ REMEDIAL WO	ORK ALTERING CASING ARILLING OPNS. PAND A
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA	IG AND ABANDON 🔲 REMEDIAL WO	ORK ALTERING CASING ARILLING OPNS. PAND A
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL	G AND ABANDON	ORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER:	REMEDIAL WO COMMENCE DE CASING/CEME	ORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed or	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Operations. (Clearly state all pertinent details,	RILLING OPNS. PAND A DATE OF AND A COMPletion And Give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). S	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Operations. (Clearly state all pertinent details,	ORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed or	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Operations. (Clearly state all pertinent details,	RILLING OPNS. PAND A DATE OF AND A COMPletion And Give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion.	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Operations. (Clearly state all pertinent details, SEE RULE 1103. For Multiple Completions:	RILLING OPNS. PAND A DATE OF AND A COMPletion And Give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log.	REMEDIAL WO COMMENCE DE CASING/CEME DEPERATIONS. (Clearly state all pertinent details, SEE RULE 1103. For Multiple Completions: Estimated cement top at 68'.	RILLING OPNS. PAND A DATE OF AND A COMPletion And Give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage 2029 HES frac'd 1st stage Pumped 71	REMEDIAL WO COMMENCE DE CASING/CEME Deperations. (Clearly state all pertinent details, DEE RULE 1103. For Multiple Completions: Estimated cement top at 68'. 2-2034', 2118'- 2121' 32 Holes 13,565 scf 70% quality nitrogen foam with 20#	RILLING OPNS. P AND A DATE OF AND
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage 2029 HES frac'd 1st stage Pumped 71 Patterson perf'd 2nd stage 1076	REMEDIAL WO COMMENCE DE CASING/CEME Deperations. (Clearly state all pertinent details, Deperations.) Estimated cement top at 68'. 2-2034', 2118'-2121' 32 Holes 13,565 scf 70% quality nitrogen foam with 20# 5'-1080', 1117'-1120', 1224'-1230' 52 Holes	RILLING OPNS. PAND A DATE OF AND A DATE OF A
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42	REMEDIAL WO COMMENCE DE CASING/CEME TIPLE COMPL CASING/CEME OTHER: Deperations. (Clearly state all pertinent details, SEE RULE 1103. For Multiple Completions: Estimated cement top at 68'. 2-2034', 2118'-2121' 32 Holes 13,565 scf 70% quality nitrogen foam with 20# 5'-1080', 1117'-1120', 1224'-1230' 52 Holes 12,622 scf 70% quality nitrogen foam with 20# L	RILLING OPNS. PAND A NT JOB Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 7: Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 799.	REMEDIAL WO COMMENCE DE CASING/CEME DIPLE COMPL CASING/CEME OTHER: Deperations. (Clearly state all pertinent details, SEE RULE 1103. For Multiple Completions: Estimated cement top at 68'. 2-2034', 2118'-2121' 32 Holes 13,565 scf 70% quality nitrogen foam with 20# 5'-1080', 1117'-1120', 1224'-1230' 52 Holes 12,622 scf 70% quality nitrogen foam with 20# L -803', 876'-881', 916'-919', 970'-973' 60 Hole	RILLING OPNS. PAND A NT JOB Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 7992 HES frac'd 3rd stage - Pumped 41	REMEDIAL WO COMMENCE	RILLING OPNS. PAND A NT JOB Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. The completion Mand Service of the completion of th
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 7992 HES frac'd 3rd stage - Pumped 41	REMEDIAL WO COMMENCE DE CASING/CEME DIPLE COMPL CASING/CEME OTHER: Deperations. (Clearly state all pertinent details, SEE RULE 1103. For Multiple Completions: Estimated cement top at 68'. 2-2034', 2118'-2121' 32 Holes 13,565 scf 70% quality nitrogen foam with 20# 5'-1080', 1117'-1120', 1224'-1230' 52 Holes 12,622 scf 70% quality nitrogen foam with 20# L -803', 876'-881', 916'-919', 970'-973' 60 Hole	RILLING OPNS. PAND A NT JOB Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. The completion Mand Service of the completion of th
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 7992 HES frac'd 3rd stage - Pumped 41	REMEDIAL WO COMMENCE	RILLING OPNS. PAND A NT JOB Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. The completion Mand Service of the completion of th
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 7st Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 799st HES frac'd 3rd stage - Pumped 44 05/02/06 RIH tubing, rods and pump. W	REMEDIAL WO COMMENCE DE CASING/CEME DIPLE COMPL CASING/CEME DEPARTMENT DEPART	RILLING OPNS. PAND A COMPletion Completion Completion Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. The argel with 72,620 lbs 16/30 sand. The argel with 77,566 lbs 16/30 sand. The argel with 77,566 lbs 16/30 sand.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 7: Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 799: HES frac'd 3rd stage - Pumped 44 05/02/06 RIH tubing, rods and pump. W	REMEDIAL WO COMMENCE DE CASING/CEME DIPLE COMPL CASING/CEME OTHER: Deparations. (Clearly state all pertinent details, DEE RULE 1103. For Multiple Completions: Estimated cement top at 68'. 2-2034', 2118'-2121' 32 Holes 13,565 sef 70% quality nitrogen foam with 20# 5'-1080', 1117'-1120', 1224'-1230' 52 Holes 12,622 sef 70% quality nitrogen foam with 20# L-803', 876'-881', 916'-919', 970'-973' 60 Hole 10,718 sef 70% quality nitrogen foam with 20# Vell is ready to be tested and put on productions true and complete to the best of my knowle	RILLING OPNS. PAND A DATE AND A COMPletion Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. The argel with 72,620 lbs 16/30 sand. The argel with 77,566 lbs 16/30 sand.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 7: Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 799: HES frac'd 3rd stage - Pumped 44 05/02/06 RIH tubing, rods and pump. W	REMEDIAL WO COMMENCE DE CASING/CEME DIPLE COMPL CASING/CEME OTHER: Deparations. (Clearly state all pertinent details, DEE RULE 1103. For Multiple Completions: Estimated cement top at 68'. 2-2034', 2118'-2121' 32 Holes 13,565 sef 70% quality nitrogen foam with 20# 5'-1080', 1117'-1120', 1224'-1230' 52 Holes 12,622 sef 70% quality nitrogen foam with 20# L-803', 876'-881', 916'-919', 970'-973' 60 Hole 10,718 sef 70% quality nitrogen foam with 20# Vell is ready to be tested and put on productions true and complete to the best of my knowle	RILLING OPNS. PAND A COMPletion Completion Completion Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. The argel with 72,620 lbs 16/30 sand. The argel with 77,566 lbs 16/30 sand. The argel with 77,566 lbs 16/30 sand.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 7: Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 799: HES frac'd 3rd stage - Pumped 44 05/02/06 RIH tubing, rods and pump. W	REMEDIAL WO COMMENCE DE CASING/CEME	RILLING OPNS. PAND A DATE AND A D
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). So or recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3nd stage - 7992 HES frac'd 3nd stage - Pumped 41 05/02/06 RIH tubing, rods and pump. We grade tank has been/will be constructed or closed at the constructed or close	REMEDIAL WO COMMENCE DE CASING/CEME	RILLING OPNS. PAND A DATE 06/12/06
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). So or recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3nd stage - 7992 HES frac'd 3nd stage - Pumped 41 05/02/06 RIH tubing, rods and pump. We stage that the information above grade tank has been/will be constructed or closed at SIGNATURE	REMEDIAL WO COMMENCE DE CASING/CEME	RILLING OPNS. PAND A DATE 06/12/06
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). So or recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3nd stage - 7992 HES frac'd 3nd stage - Pumped 41 05/02/06 RIH tubing, rods and pump. We stage that the information above grade tank has been/will be constructed or closed at SIGNATURE	REMEDIAL WO COMMENCE DE CASING/CEME	RILLING OPNS. PAND A DATE 06/12/06
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 71 Patterson perf'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - Pumped 42 Patterson perf'd 3rd stage - 7993 HES frac'd 3rd stage - Pumped 44 05/02/06 RIH tubing, rods and pump. W	REMEDIAL WO COMMENCE DE CASING/CEME	RILLING OPNS. PAND A NT JOB Completion Mand give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Linear gel with 6,840 lbs 16/30 sand. Inear gel with 72,620 lbs 16/30 sand. Inear gel with 77,566 lbs 16/30 sand. DATE 06/12/06 D.com Telephone No. (505) 445-6785
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or completed of starting any proposed work). Sor recompletion. 04/19/06 Patterson ran Cement Bond Log. 04/27/06 Patterson perf'd 1st stage - 2029 HES frac'd 1st stage - Pumped 7: Patterson perf'd 2nd stage - 1076 HES frac'd 2nd stage - Pumped 42 Patterson perf'd 3rd stage - 799: HES frac'd 3rd stage - Pumped 44 05/02/06 RIH tubing, rods and pump. W I hereby certify that the information above grade tank has been/will be constructed or closed a SIGNATURE Shirley A Mitchell	REMEDIAL WO COMMENCE DE CASING/CEME	RILLING OPNS. PAND A DATE 06/12/06