MERCINED NMOCD. SANTA FE 2008 OCT 14 PM 2 57 UNITED STATES FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 (April 2004) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM - 571096. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Oil Well XX Gas Well Other 8. Well Name and No. Chupadera #1 2. Name of Operator SLAYTON RESOURCES INC. 9. API Well No. P. O. BOX 2035 30-053-89011 **20019** 3a Address No. (include area code) ROSWELL, NM 88201 10. Field and Pool, or Exploratory Area Wildcate 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 907' FSL & 945' FEL Sec 23-T3S-R6E Socorro, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Water Shut-Off Production (Start/Resume) Deepen X Notice of Intent Alter Casing Well Integrity Fracture Treat Reclamation Casing Repair New Construction Other Recomplete Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Mive in Pulling unit, rig up, lower TBG and tag out. Pull all tubing and strap for depth. Strip heads, valves ect. Load out all pipe, heads, tank and misc parts. Leave-location and turn over to ranch owner: 14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Title Paul Slayton

Signatur

Date September 24, 2008

SHACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereor

Title 18 U.S.C. Section 1991 and ritle of the S.C. Section 1212, make it a crime for any person k States any false, ficultions or fraudulent, statements or representations as to any matter within i

Accepted For Record Only! See Attached For Correct Form Required For Water Well Conversion.

3160-4 - CONVERSION TO WATER WELL

Format for a Release Agreement--Patented Surface

RELEASE AGREEMENT

KNOW ALL MEN BY THESE PRESENTS, that I
of the County of in the State of
am the surface owner of the hereinafter described land upon which a well for
oil or gas was drilled, to wit:
Operator
Lease Number
Lessee
Well No. (1/4 1/4) Sec. , Twp. , Rge
1011 100
The well is located from the line and
feet from the line of Sec
I do hereby notify the Bureau of Land Management of my desire to utilize said
well as a water supply well and I do hereby release and discharge the
operator, lessee, and the Bureau of Land Management from any further work or
responsibility in relation to the plugging of said well.
WITNESS by hand and seal this day of, 19
Surface Owner
Bullace Owner
Address
IN THE PRESENCE OF:
Addmood
Address
Address
11002000