Office State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-021-20123
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	L-5813
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7 Loore Name on Livit Assessment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	WBDGU
PROPOSALS.)	8. Well Number 032F
1. Type of Well: Oil Well Gas Well Other CO2 Gas Well 2. Name of Operator	9. OGRID Number 495
Hess Corporation	9. OOKID Nulliber 493
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 840, Seminole, Texas 79360	West Bravo Dome CO2 Gas
4. Well Location	1
Unit Letter F: 1650 feet from the North line and 1880	Feet from the West line
Section 3 Township 19N Range 29E NI 11. Elevation (Show whether DR, RKB, RT, GR, etc.	MPM County Harding
11. Elevation (Snow whether DR, RKB, R1, GR, etc.) 4677'	
[1947] 化高温速度 建氯化物 化基础 医多种	(1) 2011年7月1日 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 11 (1) 1
12 Charle Ammaniata Day to Indicata Natura of Nation	Day and an Other Date
12. Check Appropriate Box to Indicate Nature of Notice,	Report of Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR	and the second s
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	_
DOWNHOLE COMMINGLE	
_	_
OTHER: OTHER: Chang	e out tbg. valve
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.	tach wellbore diagram of proposed completion
of recompletion.	
10/3 MI Key Pressure Truck, JSA, TPC 700 psi, CPC 0 psi. RU and Pump	down Tbg w/8 bbls 6% KCL. Change
out Tbg Valve, Drop 4 Soap Sticks, open Well to Tank, Rec 8 BLW. SI We	
Spud Date: Rig Release Date:	
Spud Date: Rig Release Date:	
Spud Date: Rig Release Date:	
Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
	e and belief.
I hereby certify that the information above is true and complete to the best of my knowledg	
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Engineering Technician	DATE_11/21/08
I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLEEngineering Technician Type or print nameRita C. Smith E-mail address:rsmith@hess.com	DATE_11/21/08
I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLE Engineering Technician Type or print nameRita C. Smith E-mail address:rsmith@hess.com For State Use Only	DATE11/21/08 PHONE:(432) 758-6726
I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLEEngineering Technician Type or print nameRita C. Smith E-mail address:rsmith@hess.com	DATE11/21/08 PHONE:(432) 758-6726