

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

2008 DEC 29 PM 1:04

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-021-20043
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/> CO2 Supply		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Hess Corporation		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 840 Seminole, Texas 79360		7. Lease Name or Unit Agreement Name Mitchell
4. Well Location Unit Letter C_: 660 feet from the North line and 1980 feet from the West line Section 8 Township 18N Range 30E NMPM County Harding		8. Well Number 081C
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4401' GL		9. OGRID Number 495
		10. Pool name or Wildcat West Bravo Dome CO2 Gas

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Install new tbg. & packer ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/04/08 MIRU Key #426, csg 580 psi, tbg 580 psi, blow down csg, kill tbg. & ND wellhead. Install new wellhead, NU BOP, TOO H w/55 jts tbg, tbg parted in collar @ jt. 56. PU & TIH w/workstring, screw into fish, TOO H w/5 jts tbg & pkr. TIH w/workstring, tag @ 1996', TOO H LD workstring, SWI.  
11/05/08 Csg 280 psi, kill well, PU & TIH w/Arrow Set I packer w/on/off tool & 60 jts 2-3/8" tbg, set @ 1856', displace w/ Packer fluid. Test csg to 5000 F/20 min, ND BOP, NU hanger flange. Set slips w/10k in tension, install valve, SWI.  
11/10/08 Csg. 580 psi, tbg 580 psi, kill well, J off on/off tool. TOO H & LD 60 jts 2-3/8" tbg, had 6 cracked collars, did not Have enough new tbg in yard. SWI wait on tbg f/Seminole.  
11/11/08 Csg 280 psi, kill well, PU & TIH w/61 jts 2 3/8" tbg J into on/off tool & displace packer fluid. Test csg to 500 psi f/20 min, good. ND BOP, NU hanger flange, set 10k on slips in tension. Install valve, RDPU.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C. Smith TITLE Engineering Technician DATE 12/22/2008

Type or print name Rita C. Smith E-mail address: rsmith@hess.com PHONE: (432) 758-6726

For State Use Only

APPROVED BY: Ed Martz TITLE DISTRICT SUPERVISOR DATE 2/9/09  
Conditions of Approval (if any):