

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

2009 SEP 25 AM 11 40

WELL API NO. 30-021-20490
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L05777-4
7. Lease Name or Unit Agreement Name: Bravo Dome Carbon Dioxide Gas Unit 2029
8. Well Number 361
9. OGRID Number 16696
10. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas 160
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4643.6' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other CO2 Supply Well <input type="checkbox"/>	7. Lease Name or Unit Agreement Name: Bravo Dome Carbon Dioxide Gas Unit 2029
2. Name of Operator OXY USA Inc.	8. Well Number 361
3. Address of Operator P.O. Box 4294 Houston, TX 77210-4294	9. OGRID Number 16696
4. Well Location Unit Letter <u>J</u> : <u>1715</u> feet from the <u>S</u> line and <u>1900</u> feet from the <u>E</u> line Section <u>36</u> Township <u>20N</u> Range <u>29E</u> NMPM County <u>Harding</u>	10. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas 160

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Spud Date: 10/10/08 Rig Release Date: 10/21/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Sr. Regulatory Analyst DATE 09/23/09  
Type or print name Kimberly Long E-mail address: Kimberly\_Long@oxy.com PHONE 713-215-7643

For State Use Only

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 10/2/09  
Conditions of Approval (if any):

See Attachment

**Attachment to Form C-103 for the OXY Bravo Dome Unit Well  
2029-361J, API 30-021-20490, J-36- 20 North 29 East**

Well Completion status of **Temporary Abandonment** is hereby approved for the above well per 19.15.25.14 (3) shown below.

**19.15.25.14 DEMONSTRATING MECHANICAL INTEGRITY:**

**A.** An operator may use the following methods of demonstrating internal casing integrity for wells to be placed in approved temporary abandonment:

**(1)** the operator may set a cast iron bridge plug within 100 feet of uppermost perforations or production casing shoe, load the casing with inert fluid and pressure test to 500 psi surface pressure with a pressure drop of not more than 10 percent over a 30 minute period;

**(2)** the operator may run a retrievable bridge plug or packer to within 100 feet of uppermost perforations or production casing shoe, and test the well to 500 psi surface pressure for 30 minutes with a pressure drop of not greater than 10 percent over a 30 minute period; or

**(3)** the operator may demonstrate that the well has been completed for less than five years and has not been connected to a pipeline.