

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
222 South St. Francis Dr.  
Santa Fe, NM 87505

2010 AUG 16 P 1:59

WELL API NO. 30-021-20412
5. Indicate Type of Lease <input checked="" type="checkbox"/> Federal STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NMNM-27898
7. Lease Name or Unit Agreement Name West Bravo Dome Unit
8. Well Number 0310
9. OGRID Number 495
10. Pool name or Wildcat (96387) West Bravo Dome CO2 Gas
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5384'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other CO2 Supply

2. Name of Operator  
Hess Corporation

3. Address of Operator PO Box 840  
Seminole TX 79360

4. Well Location  
Unit Letter O : 1200 feet from the SOUTH line and 1800 feet from the EAST line  
Section 3 Township 18N Range 29E NMPM County HARDING

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
5384'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: Frac Well



SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER:



13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Intent to do work week of 8/23/2010

The procedures for the fracs are:

MIRU

Kill well

Frac pump schedule

RDMO Halliburton

Flow back to frac tank until sand production ceases or 72 hrs (whichever

Put down production line.

Spud Date:

5/29/2010

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Rita C. Smith*

TITLE Engineering Tech

DATE 8/12/2010

Type or print name Rita C. Smith

E-mail address: rsmith@hess.com

PHONE: 432-758-6726

For State Use Only

APPROVED BY:

*Ad Martin*

TITLE

DISTRICT SUPERVISOR

DATE

8/17/10

Conditions of Approval (if any):