Office	of New Mexico	Form C-103
District I Energy, Mine	rals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-021-20508
1301 W. Grand Ave., Artesia, NM 88210 OIL CONST	ERVATION DIVISION	5. Indicate Type of Lease
1000 Pio Provos P.d. Arton NIM 97410	outh St. Francis Dr.	STATE FEE 🛣
District IV 1220 S. St. Francis Dr., Santa Fe, NM	a Fe, NM 87505	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Mitchell
1. Type of Well: Oil Well Gas Well Other CO2 SUPPLY		8. Well Number 181B
2. Name of Operator HESS Corporation		9. OGRID Number 495
3. Address of Operator PO Box 840		10. Pool name or Wildcat (96387)
Seminole TX	79360	West Bravo Dome CO2 Gas
4. Well Location  Unit Letter B: 1200 feet from the NORTH line and 1650 feet from the EAST line		
Unit Letter B : 1200 feet from the NORTH line and 1650 feet from the EAST line Section 18 Township 18N Range 30E NMPM County HARDING		
11. Elevation (Short	w whether DR, RKB, RT, GR, etc.)	
4503' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANG		
TEMPORARILY ABANDON	COMMENCE DRIL	<del></del>
PULL OR ALTER CASING   MULTIPLE COMPL	_ CASING/CEMENT	JOB 📙
DOWNHOLE COMMINGLE		
~ ~		
OTHER: Gas Gun	▼ OTHER:	
13. Describe proposed or completed operations. (Cl	early state all pertinent details, and	give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19.	early state all pertinent details, and	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.	early state all pertinent details, and	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Con	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cloof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cloud starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa.  - MIRU Renegade WL. RIH & t. RU & RIH w/ 10' Gas Gun.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conternal ter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conternal ter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa.  - MIRU Renegade WL. RIH & t. RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa.  - MIRU Renegade WL. RIH & t. RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa.  - MIRU Renegade WL. RIH & t. RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15 8' (Top of Gun).  Turn well over to	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa.  - MIRU Renegade WL. RIH & tRU & RIH w/ 10' Gas Gun.  Get on depth with CL at 209 Fire Gun. TOOH W/spent gun.  RDMO Renegade & Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15 8' (Top of Gun).  Turn well over to	productions.
13. Describe proposed or completed operations. (Cl of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15 8' (Top of Gun).  Turn well over to	productions.
13. Describe proposed or completed operations. (Clos of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15 8' (Top of Gun).  Turn well over to represent the state of my knowledge.	productions.
13. Describe proposed or completed operations. (Clos of starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15 8' (Top of Gun).  Turn well over to	productions.
13. Describe proposed or completed operations. (Clos fistering any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa.  - MIRU Renegade WL. RIH & t. RU & RIH w/ 10 ' Gas Gun.  Get on depth with CL at 209 Fire Gun. TOOH W/spent gun.  RDMO Renegade & Pump truck.  Spud Date: 5/4/2010 I I	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15 8' (Top of Gun).  Turn well over to Rig Release Date:	productions.  DATE 2/8/2011
13. Describe proposed or completed operations. (Clof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.  Spud Date: 5/4/2010 I	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15  8' (Top of Gun).  Turn well over to a sign of the content of the con	productions.  2 and belief.  DATE 2/8/2011  S.COM PHONE: 432-758-6726
13. Describe proposed or completed operations. (Clof starting any proposed work). SEE RULE 19. proposed completion or recompletion.  - MIRU Pump truck.  - Pump 8 bbls production wa  - MIRU Renegade WL. RIH & t RU & RIH w/ 10' Gas Gun. Get on depth with CL at 209 Fire Gun. TOOH W/spent gun. RDMO Renegade & Pump truck.  Spud Date: 5/4/2010 I	early state all pertinent details, and 15.7.14 NMAC. For Multiple Conter in well.  ag water level (15  8' (Top of Gun).  Turn well over to a sign of the content of the con	productions.  DATE 2/8/2011