

From: [Jordan Kessler](#)
To: [Lowe, Leonard, EMNRD](#)
Subject: [EXTERNAL] Minor change to pending NSL application
Date: Wednesday, August 17, 2022 10:55:46 AM
Attachments: [image001.png](#)
[RUTHLESS 11 FED COM 722H 30-025-50462.pdf](#)
[Ruthless 11 Fed Com 722H NSL for filing.pdf](#)

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Dear Mr. Lowe,

EOG has a pending NSL application that I submitted on July 26 (submission ID 128734; reference pLEL2220940954) (application attached). The NSL request is for the Ruthless 11 Fed Com 722H well (API No. 30-025-**47727**). In commencing work on the vertical portion of the well, EOG encountered problems with a cellar/conductor pipe failure. Accordingly, after close coordination with the BLM and OCD, EOG is substituting out a pending APD to be drilled at the non-standard location previously requested for the 722H well. The well name will continue to be the Ruthless 11 Fed Com No. 722H. The BLM and OCD have approved a new API number for the well, which is 30-025-**50462**.

The surface hole location is slightly changed because of the existence of the original well that failed. However, the proposed completed interval is identical and everything else remains the same. Accordingly, I believe it is appropriate to substitute the API number for the existing (pending application), but please let me know if you think otherwise. Please feel free to give me a call if you'd like to talk this one through.

Thanks!

Jordan

Jordan Kessler

Senior Regulatory Advisor



125 Lincoln Avenue, Suite 213

Santa Fe, NM 87501

Mobile: (432) 488-6108

Office: (575) 748-4158

jordan_kessler@eogresources.com