State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
nMUB 1/2515/291 OPER						TOR		[Initia	l Report 🛛 🗵	Final Report	
Name of Company						Contact						
Yates Petroleum Corporation 25575						Amber Cannon Talanhara Na						
Address 105 S. 4 TH Street						Telephone No. 575-748-1471						
Facility Name API Number						Facility Type						
Graham AKB State #8 30-015-31913						Well						
Surface Owner Mineral Owner						Lease No.					}	
State State					Owner				V-2705			
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		/South Line Fect from the East/West Line County						
$\begin{array}{c c} E \\ E \\ 2 \\ 22S \\ 31E \\ \end{array}$			1650					Vest Eddy				
Latitude <u>32.42303</u> Longitude <u>103.75557</u>												
NATURE OF RELEASE												
Type of Release Produced Water / Crude Oil						Volume of Release 42 B/PW; 6 B/O			Volume Recovered 0 B/PW, 0 B/O			
Source of Release						Date and Hour of Occurrence			Date and Hour of Discovery			
Poly flowline						8/7/2011; PM			8/7/2011; PM			
Was Immediate Notice Given? Xes No Not Require						If YES, To Whom? d Mike Bratcher/NMOCD II						
By Whom?						Date and Hour						
Robert Asher/Yates Petroleum Corporation						8/8/2011; PM						
Was a Watercourse Reached?						N/A						
Yes No Not Required Mike Bratcher/NMOCD II By Whom? Date and Hour By 8/2011; PM Robert Asher/Yates Petroleum Corporation 8/8/2011; PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse Reached? Yes No N/A OCT Describe Cause of Problem and Remedial Action Taken * A poly flowline busted. The well was shut in as well as the knockout (located at the battery). Personnel were called in to fix the prured poly pipe. Describe Area Affected and Cleanup Action Taken *											RIE	
Describe Cause of Problem and Remedial Action Taken *												
A poly flowl	A poly flowline busted. The well was shut in as well as the knockout (located at the battery). Personnel were called in to fix that buy pupe. Describe Area Affected and Cleanup Action Taken *											
1963611007116	a mootou	und Creanup i	ietion iu				ng unit along leas			•		
impacted soil	ls were exca	avated and tak	ten to an N	MOCD approve	d facility	. Vegetation	within the impac	ted area	will be spr	ayed with micro	blaze Vertical	
							lorides for docur					
BTEX are un	ider RRAL' k plan will	's (site ranking	g is 0) a F to the OCl	inal Report, C-14	H will be und Wa	submitted to ter: >100 ? (1)	the OCD request 25', Section 2, T	ing clos	ure. If the	analytical result rend Man) Wel	s are above the	
							IS 0. Based on in					
							0, Yates Petroleu					
I hereby certi	fy that the	information g	iven abov	e is true and com	plete to the	he best of my	knowledge and u	indersta	nd that pur	suant to NMOC	D rules and	
nublic health	or the envi	ronment The	o report a	ce of a C-141 rep	release n	e NMOCD m	nd perform correct arked as "Final R	enort" d	oes not rel	ieve the operato	r of liability	
should their o	operations h	nave failed to	adequately	y investigate and	remediat	e contaminati	ion that pose a thi	eat to gi	ound wate	r, surface water,	human health	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.												
Signature amber Cannon												
Signature	Inh	in Car	Λ		All k							
_	-				Approved by District Supervisor							
Printed Name. Amber Cannon												
Title: Environmental Regulatory Agent						Approval Da	OCT 19 2		Expiration	Date: NA		
E-mail Address_acannon@yatespetroleum.com						Conditions of Approval.]	
Date Wedne	sday, Octol	ber 19, 2011	one 575-748-41	11	2RP-875	7	Inal	/				

Date Wednesday, October 19, 2011 * Attach Additional Sheets If Necessary

1