


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW1301753978

OPERATOR Initial Report Final Report

Name of Company: Linn Operating 269324	Contact: Jose Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: J.L. Keel B #72	Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001528580
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	05	17S	31E	2230	South	760	East	Eddy

Latitude: 32.86242 Longitude: -103.88504

NATURE OF RELEASE

Type of Release: Produced Water / Oil
Source of Release: 2" Fiberglass HP line
Was Immediate Notice Given? Yes No Not Required
By Whom? Jose Hernandez
Was a Watercourse Reached? Yes No
If a Watercourse was Impacted, Describe Fully.*:

Volume of Release: 35 bbls / 5 bbls
Date and Hour of Occurrence: 01/08/2013 9:30 am
If YES, To Whom? M. Bratcher - NM OCD Terry Gregston-BLM
Date and Hour 01/09/2013 9:45am
If YES, Volume Impacting the Watercourse.

Volume Recovered: 0 / 0
Date and Hour of Discovery: 01/09/2013 9am

Describe Cause of Problem and Remedial Action Taken.*: On 1-8-13 at 2130 Received alarm at Keel West for header discharge pressure. Line was shut in. Could not locate spill in dark. Found Leak on 1-9-13 at 0900. Leak was caused by failure in line at 2" collar.

Describe Area Affected and Cleanup Action Taken.*: Leak was located approximately 400' NE of J.L. Keel B #72. 2" Fiberglass HP Line was located 5' on E side of lease Rd. Spill covered 250' by 10' average S on lease Rd. and on side of Rd. in sandy soil. Estimated 40 BBL total. All fluids lost.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:
Printed Name: Joe Hernandez
Title: Production Foreman

OIL CONSERVATION DIVISION

Approved by District Supervisor:
SIGNED BY Mike Bennett
Approval Date: **JAN 17 2013** Expiration Date:

E-mail Address: jhernandez@linneer.com
Date: 01/10/2013 Phone: 575-942-9492

Conditions of Approval: Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**
Attached


February 17, 2013

* Attach Additional Sheets If Necessary

2 P-1505

Bratcher, Mike, EMNRD

From: Theresa McCracken <TMcCracken@linnenergy.com>
Sent: Thursday, January 10, 2013 8:07 AM
To: Bratcher, Mike, EMNRD; tgregsto@blm.gov
Cc: Chris Golding; Thomas Butters; Debra Gordon; Nancy Fitzwater; Terry Callahan; Ron Ragland; Joe Hernandez; Gary Wink
Subject: Linn- JL Keel B 72 Initial C-141
Attachments: JL Keel B # 72 01-09-13 .pdf



Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator
LINN Energy, LLC
2130 W Bender
Hobbs, NM 88240
T: 575-738-1739 / F: 575-738-1740
tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.