


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*njmw/301851859*

**OPERATOR**  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Folk Federal B	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-36862
					Closest well

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	17S	29E					Eddy

Latitude 32 50.183 Longitude 104 5.516

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	90bbls Oil 100bbls Produced water	Volume Recovered	70bbls Oil 80bbls Produced Water
Source of Release	Heater treater	Date and Hour of Occurrence	12/30/2012	Date and Hour of Discovery	12/30/2012 4:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD Jim Amos-BLM Terry Gregston-BLM			
By Whom?	Michelle Mullins	Date and Hour	12/31/2012 9:30 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The fire-tube gasket malfunctioned on the heater treater and caused the release of fluid. The heater treater has been repaired and returned to service.

Describe Area Affected and Cleanup Action Taken.\*

Initially 190bbls were released from the heater treater at the facility and we were able to recover 150bbls with a vacuum truck. The majority of the release was contained inside the lined facility. There was some overspray from the release in the adjacent pasture area outside of the facility berm. The facility has been returned to its prior condition. Tetra Tech will sample the release area outside of the lined facility to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josh Russo		Approved by District Supervisor:	Signed By:
Title: Senior Environmental Coordinator		Approval Date: <b>JAN 18 2013</b>	Expiration Date:
E-mail Address: jrusso@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/10/2013 Phone: 432-212-2399		Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 18, 2013</b>	

\* Attach Additional Sheets If Necessary

**2RP-1506**

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo <jrusso@concho.com>  
**Sent:** Thursday, January 10, 2013 12:23 PM  
**To:** Bratcher, Mike, EMNRD; James A Amos (jamos@blm.gov)  
**Cc:** Ike Tavarez (ike.tavarez@tetrattech.com); Robert Grubbs (Robert.Grubbs@tetrattech.com); Tom Franklin (tom.k.franklin@tetrattech.com)  
**Subject:** C-141 Initial Report - Folk Federal B Tank Battery  
**Attachments:** FOLK FEDERAL B TANK BATTERY -- DATE OF RELEASE -- 12-30-2012.pdf

Mr. Bratcher, Mr. Amos,

Please see attached the C-141 Initial Report for a release that occurred at our Folk Federal B Tank Battery on 12/30/2012.

Thank you,

**Joshua Russo**

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

[jrusso@concho.com](mailto:jrusso@concho.com)

*Mailing Address:*

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

## Bratcher, Mike, EMNRD

---

**From:** Michelle Mullins <MMullins@concho.com>  
**Sent:** Monday, December 31, 2012 8:30 AM  
**To:** Bratcher, Mike, EMNRD; Amos, James A; Gregston, Terry G  
**Cc:** Joshua Russo  
**Subject:** Folk Federal B-Immediate Notification

Mr. Bratcher, Mr. Amos, Ms. Gregston:

At approximately 4:00 p.m. on 12/30/2012, a produced fluid release was discovered at the above-referenced facility. An estimated 200 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

32 50 10.91 104 05 26.75

Folk Federal #10  
Unit H Sec 17 T 17S R 29E  
Eddy County, NM  
NMNM-0397623

Turn north at MM 125 (County road 211), travel 1.3 miles, turn east. Travel .3 miles to battery.

Michelle Mullins  
HSE Field Tech  
2407 Pecos Avenue  
P.O. Box 1630  
Artesia, NM 88211-1630  
Phone: (575)746-2010  
Cell: (432) 934-1052  
[mmullins@conchoresources.com](mailto:mmullins@conchoresources.com)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**Bratcher, Mike, EMNRD**

---

**From:** Amos, James <jamos@blm.gov>  
**Sent:** Monday, December 31, 2012 11:06 AM  
**To:** Michelle Mullins  
**Cc:** Bratcher, Mike, EMNRD; Gregston, Terry G; Joshua Russo  
**Subject:** Re: Folk Federal B-Immediate Notification

Michelle, I will need some additional information. Was the spill inside the firewall? Lined/unlined? On/off pad? Get back to me. thanks

On Mon, Dec 31, 2012 at 8:29 AM, Michelle Mullins <MMullins@concho.com> wrote:

Mr. Bratcher, Mr. Amos, Ms. Gregston:

At approximately 4:00 p.m. on 12/30/2012, a produced fluid release was discovered at the above-referenced facility. An estimated 200 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

32 50 10.91 104 05 26.75

Folk Federal #10

Unit H Sec 17 T 17S R 29E

Eddy County, NM

NMNM-0397623

Turn north at MM 125 (County road 211), travel 1.3 miles, turn east. Travel .3 miles to battery.

Michelle Mullins

HSE Field Tech  
2407 Pecos Avenue  
P.O. Box 1630

Artesia, NM 88211-1630  
Phone: (575)746-2010  
Cell: (432) 934-1052  
[mmullins@conchoresources.com](mailto:mmullins@conchoresources.com)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo <jrusso@concho.com>  
**Sent:** Monday, December 31, 2012 7:19 PM  
**To:** 'jamos@blm.gov'  
**Cc:** Bratcher, Mike, EMNRD; 'tgregsto@blm.gov'; Michelle Mullins  
**Subject:** Re: Folk Federal B-Immediate Notification

Mr. Amos,

The subject release occurred inside the lined facility of the Folk Federal B Tank Battery. There was some overspray into the adjacent pasture.

We will submit a C-141 report with additional details.

Thank you,

Joshua Russo  
Sr. Environmental Coordinator  
432.683.7443 (main)  
432.685.4381 (direct)  
432.212.2399 (cell)  
[jrusso@concho.com](mailto:jrusso@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Amos, James [<mailto:jamos@blm.gov>]  
**Sent:** Monday, December 31, 2012 12:06 PM  
**To:** Michelle Mullins  
**Cc:** [mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us) <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Gregston, Terry G <[tgregsto@blm.gov](mailto:tgregsto@blm.gov)>; Joshua Russo  
**Subject:** Re: Folk Federal B-Immediate Notification

Michelle, I will need some additional information. Was the spill inside the firewall? Lined/unlined? On/off pad? Get back to me. thanks

On Mon, Dec 31, 2012 at 8:29 AM, Michelle Mullins <[MMullins@concho.com](mailto:MMullins@concho.com)> wrote:

Mr. Bratcher, Mr. Amos, Ms. Gregston:

At approximately 4:00 p.m. on 12/30/2012, a produced fluid release was discovered at the above-referenced facility. An estimated 200 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

32 50 10.91 104 05 26.75

Folk Federal #10

Unit H Sec 17 T 17S R 29E

Eddy County, NM

NMNM-0397623

Turn north at MM 125 (County road 211), travel 1.3 miles, turn east. Travel .3 miles to battery.

Michelle Mullins

HSE Field Tech  
2407 Pecos Avenue  
P.O. Box 1630  
Artesia, NM 88211-1630  
Phone: (575)746-2010  
Cell: (432) 934-1052  
[mmullins@conchoresources.com](mailto:mmullins@conchoresources.com)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained

herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.