District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

Form C-141 Revised October 10, 2003

AUG 1 3 2013
District Office in accordance
NMOCD ARTESIA HR Rule 116 on back
side of form

Release Notification and Corrective Action	
NJMW 1322828129 OPERATOR Initial Report Final Report	
Name of Company COG OPERATING LLC 229/37 Contact Pat Ellis Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077	
Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077 Facility Name Arabian 6 Fee #001 Facility Type Tank Battery	
Surface Owner Private Mineral Owner	Lease No. (API#) 30-015-39405
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the North	South Line Feet from the East/West Line County Eddy
Latitude 32.68414 Longitude 104.42859	
NATURE OF RELEASE	
Type of Release 100bbls of produced water	Volume of Release 100bbls Volume Recovered 90bbls
Source of Release Water tank	Date and Hour of Occurrence O7-31-2013 Date and Hour of Discovery O7-31-2013 3:30pm
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM
By Whom? Michelle Mullins	Date and Hour 08-01-2013 07:44am
Was a Watercourse Reached? ☐ Yes ☑ No	If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.*	
Lightning struck the spare water tank. Replaced water tank.	
Describe Area Affected and Cleanup Action Taken,*	
Initially 100bbls of produced water were released due to a lightning strike on one of our fiberglass tanks. We were able to recover 90bbls of produced water. The entire release was contained inside the lined facility. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary This facility has been returned to its prior condition.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
	OIL CONSERVATION DIVISION
Signature:	1.1
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor: Signed By Mily Branchese
Title: Senior Environmental Coordinator	Approval Date: Expiration Date:
E-mail Address: rgrubbs@concho.com	Conditions of Approval:
Date: 08-13-2013 Phone: 432-661-6601	Remediation per OCD Rule &
Attach Additional Sheets If Necessary	Guidelines. SUBMIT REMEDIATION 7 RP-1833
	September 16, 2013

From: Robert Grubbs <RGrubbs@concho.com>

Sent: Tuesday, August 13, 2013 4:16 PM

To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)

Cc: Robert McNeill; Tavarez, Ike; Kujawski, Marcus (Marcus.Kujawski@tetratech.com)


Subject: C-141 Initial Report - Arabian 6 Fee #003H and the Burch Keely Unit #205

Attachments: Arabian 6 Fee #001 (Tank Battery) -- Date Of Release -- 08-01-2013.pdf; Burch Keely

Unit #205 (Injection Line) -- Date Of Release -- 08-01-2013.pdf

Follow Up Flag: Flag Status:

Follow up Completed



Gentlemen.

Please see attached the C-141 Initial for a release that occurred at our Arabian 6 Fee #003H on 07-31-2013 and the Burch Kelly Unit #205 on 08-01-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grabba Jr.


Sh. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
1971bbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, August 15, 2013 1:37 PM

To:Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)Cc:Robert McNeill; Tavarez, Ike; Kujawski, Marcus (Marcus.Kujawski@tetratech.com)Subject:RE: C-141 Initial Report - Arabian 6 Fee #003H and the Burch Keely Unit #205



Gentlemen,

On the Arabian 6 Fee#1 C-141 that I had sent out on 08-13-2013 at 5:16pm is a lined facility.

Robert Grubbes Tr.

Sr. Environmental Coordinator

432.683.7443 (main) 432.818.2369 (direct)

432.661.6601 (ccll)

rgrubbs@concho.com

Mailing Address:

One Concho Center 600 W. Illinois Avenue

Midland, Texas 79701



From: Robert Grubbs

Sent: Tuesday, August 13, 2013 5:16 PM

To: Mike Bratcher (<u>mike.bratcher@state.nm.us</u>) (<u>mike.bratcher@state.nm.us</u>); Amos, James <<u>jamos@blm.gov</u>>

(jamos@blm.gov)

Cc: Robert McNeill; 'Tavarez, Ike'; Kujawski, Marcus (<u>Marcus.Kujawski@tetratech.com</u>) **Subject:** C-141 Initial Report - Arabian 6 Fee #003H and the Burch Keely Unit #205

Gentlemen,

Please see attached the C-141 Initial for a release that occurred at our Arabian 6 Fee #003H on 07-31-2013 and the Burch Kelly Unit #205 on 08-01-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.

Sr. Environmental Coordinator

432.683.7443 (main) 432.818.2369 (direct) 432.661.6601 (cell) rgrubbs@concho.com Mailing Address: Onc Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

2

From:

Bratcher, Mike, EMNRD

Sent:

Wednesday, August 14, 2013 3:01 PM

To:

Robert Grubbs (RGrubbs@concho.com)

Subject:

FW: C-141 Initial Report - Arabian 6 Fee #003H and the Burch Keely Unit #205

Attachments:

Arabian 6 Fee #001 (Tank Battery) -- Date Of Release -- 08-01-2013.pdf; Burch Keely

Unit #205 (Injection Line) -- Date Of Release -- 08-01-2013.pdf

Robert,

The attached C-141 is for the Arabian 6 Fee 1. Is there supposed to also be one for the Arabian 6 Fee 3H?

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108

C: 575-626-0857 F: 575-748-9720

From: Robert Grubbs [mailto:RGrubbs@concho.com]

Sent: Tuesday, August 13, 2013 4:16 PM

To: Bratcher, Mike, EMNRD; Amos, James < <u>jamos@blm.gov</u>> (<u>jamos@blm.gov</u>) **Cc:** Robert McNeill; Tavarez, Ike; Kujawski, Marcus (<u>Marcus.Kujawski@tetratech.com</u>) **Subject:** C-141 Initial Report - Arabian 6 Fee #003H and the Burch Keely Unit #205



Gentlemen,

Please see attached the C-141 Initial for a release that occurred at our Arabian 6 Fee #003H on 07-31-2013 and the Burch Kelly Unit #205 on 08-01-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubba Jr.
Sr. Environmental Coordinator
132.683.7113 (main)
132.818.2369 (direct)

432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From:

Michelle Mullins < MMullins@concho.com>

Sent:

Thursday, August 01, 2013 6:44 AM

To:

Amos, James (jamos@blm.gov); Bratcher, Mike, EMNRD

Cc:

Robert Grubbs

Subject:

Arabian 6 Fee #1-Immediate Notification

Mr. Amos, Mr. Bratcher:

At approximately 3:30 p.m. on 07/31/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 100 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.68414 104.42859

Arabian 6 Fee #1 Unit M Sec 6 T19S R26E 545' FSL & 380' FWL Eddy County, NM API 30-015-39405

From Artesia, travel south on Highway 285 to CR-38. Turn west, and travel 2.7 miles. Turn left and travel .9 miles. Turn left and travel .8 miles, turn right and travel .7 miles to location.

Thank you.

Michelle Mullins.
HSE Field Technician
COG Operating, LLC
(432) 934-1052.
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.