


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

nJMW 1334052817

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Federal 12 #1 South CTB	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		API No.	30-015-26742(nearest well)
---------------	-----	---------------	--	---------	----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	12	22S	31E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	45 bbls	Volume Recovered	40 bbls
Source of Release	Pump failure caused tank overflow	Date and Hour of Occurrence	11/17/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	11/19/13 @ 9:04am and 11/18/13 @ 2:07pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*


A bearing on the water transfer pump went out causing the pump to fail and the water production tank to overflow. The overflow caused 45 bbls of produced water to leak onto the ground. A vacuum truck recovered 40 bbls of the leaked fluids and the pump was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 30' x 30' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 

Printed Name: Chancey Summers

Approved by Environmental Specialist:

Signed By 

Title: HES Specialist

Approval Date:

DEC 04 2013

Expiration Date:

E-mail Address: Chancey.Summers@oxy.com

Conditions of Approval:  
Remediation per OCD Rule & Guidelines, &  
like approval by BLM. SUBMIT REMEDIATION

Attached ☐

Date: 12/2/13

Phone: (575) 397-8216

\* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:  
January 6, 2014

2RP-2097

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Wednesday, December 04, 2013 11:52 AM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141s, Federal 12 #1 South CTB  
**Attachments:** Initial C-141, Fed 12-1 CTB 12-2-13.pdf; Initial C-141, Fed 12#1 CTB 12-3-13.pdf

Attached are the initial C-141s for two leak that occurred at the Federal 12 #1 South CTB on 11/17/2013 and 11/20/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. I apologize for the delay due in part to the holidays.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## Bratcher, Mike, EMNRD

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Wednesday, December 04, 2013 2:15 PM  
**To:** 'Kathy Purvis'; jamos@blm.gov; jvancure@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** RE: Initial C-141s, Federal 12 #1 South CTB

C-141s received – Thanks,

Mike Bratcher  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
O: 575-748-1283 X108  
C: 575-626-0857  
F: 575-748-9720

---

**From:** Kathy Purvis [<mailto:kathy@bbcinternational.com>]  
**Sent:** Wednesday, December 04, 2013 11:52 AM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141s, Federal 12 #1 South CTB

Attached are the initial C-141s for two leak that occurred at the Federal 12 #1 South CTB on 11/17/2013 and 11/20/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. I apologize for the delay due in part to the holidays.

*Kathy Purvis*  
BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)