RECEIVED

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grund Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Sunta Fe, NM 87505

;

State of New Mexico Energy Minerals and Natural Resources

DEC 1 0 2013

Form C-141 Revised October 10, 2003

Oil Conservation Division MOCD ARTES Submit 2 Copies to appropriate District Office in accordance with Rule 115 on back side of form

				Sa	inta Fe	, NM 875	05			_			
Release Notification and Corrective Action													
nJMW1334452660						OPERATOR			⊠ Initio	al Report		Final Report	
Name of Co			Contact: Chris Jones										
Address: 1502 W. Commerce, Carlsbad, NM 88220						Telephone No.: 575-628-4121							
Facility Name: McKittrick Hills Central Tank Battery						Facility Type: Central Tank Battery							
Surface Owner : Federal Mineral Owner								API#:					
				LOCA	TION	OF RE	LEASE						
						South Line	Feet from the	East/V	/West Line County: Eddy				
A	14 22S 24E							1					
		L		atituda 22.20°	'	Langitud	104.4611	<u></u>		1			
Latitude 32.397740 Longitude 104.4611													
Type of Release: Mix Fluids NATURE OF RELEASE Volume of Release: 200 bbls Volume Recovered: 160 bbls													
Source of Release: Transmitter malfunction						Date and Hour of Occurrence:			Date and Hour of Discovery: 12/8/2013				
Course of Acteurs . Transmitted managemental						12/8/2013		Bale and Hour of Biscovery, 12/0/2015					
Was Immedi	ate Notice (If YES, To Whom? Email: OCD/Mike Bratcher & BLM/Jim Amos											
D. When d	71												
By Whom: O Was a Water	course Read	Date and Hour: 12/9/2013 If YES, Volume Impacting the Watercourse.											
		,, ,,											
of mixed flui 160 barrels of Describe Arc north side of I hereby cert regulations a public health should their	ids, Emerge of mixed flues a Affected location. ify that the all operators or the envi- operations I	ney response ids. The transi and Cleanup A information gi are required to ronment. The nave fuiled to	included in nitter was Action Tal iven ubove o report an acceptana adoquately	n Taken.* The tr mmediate shut-in replaced. Talon/ ken.* The area in e is true and comp nd/or file certain rec of a C-141 reportional repo	of the ta LPE was npacted lete to ti release nort by the	nk battery and contacted to was inside of my otifications are NMOCD me contaminations.	d vac trucks on so complete the site factor the carthen bern knowledge and und perform correcarked as "Final Rich that pose a the	ite to pide assession surrous understanctive active activ	ck up all str ment and conding the tr and that pur- ions for rel loes not rel round wate	anding fluid offect soil so mk battery, suant to NM cases which ieve the ope r, surface w	s. They amples. 80'x15 10CD r a may corator of rater, hu	y recovered 0' and off the ules and ndanger f liability uman health	
or the enviro	nment. In a , or local is	eddition, NMC	ICD accu ilations.	stance of a C-141	report d	oes not relie	e the operator of	respons	ibility for c	ompliance	with an	y other	
							OIL CON	SERV	ATION	DIVISI	<u>NC</u>		
Signature:	Signature:						1.1						
Printed Name: Chris Jones						Approved by District Supervisorgned By Mile Branches							
Title: HES Specialist						Approval Datte 1 0 2013 Expiration Date:							
E-mail Address: Christopher Jones@ocy.com						Conditions of Approval: ination per OCD Rule & Guidelines, &							
Date: 12/1	0/2013	Phone: 57	5- <u>62</u> 8-412				1. <u>SUBMIT REN</u>						
* Attach Add	1133	44519	912	-	$\neg \frac{P}{P}$		NO LATER THA		7	RP-	-21	07	
iJMV	1133	4453	269	6									

Warren, JeanMarie, EMNRD

From: Christopher_Jones@oxy.com

Sent: Monday, December 09, 2013 8:53 AM

To: Bratcher, Mike, EMNRD; Warren, JeanMarie, EMNRD; jamos@blm.gov;

jvancure@blm.gov

Cc: dadkins@talonlpe.com; kwilson@talonlpe.com; Tiffney_Burkham@oxy.com

Subject: Spill at the McKittrick CTB

This is to inform you that Oxy had a leak at the McKittrick CTB on 12-8-13. Best guess leak was caused from a frozen transmitter on the water tank. Transmitter did not trip the transfer pump nor did it send out a high tank level alarm. Causing the tanks to equalize and run over. Oxy released 100 bbls produced water and 100 bbls oil, 50 bbls oil has been recovered. Leak ran off location about 2/10 of a mile. Talon will be going out to do some initial delineation, a c141 will follow.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com

Sent: Monday, December 09, 2013 8:53 AM

To: Bratcher, Mike, EMNRD; Warren, JeanMarie, EMNRD; jamos@blm.gov;

jvancure@blm.gov

Cc: dadkins@talonlpe.com; kwilson@talonlpe.com; Tiffney_Burkham@oxy.com

Subject: Spill at the McKittrick CTB

This is to inform you that Oxy had a leak at the McKittrick CTB on 12-8-13. Best guess leak was caused from a frozen transmitter on the water tank. Transmitter did not trip the transfer pump nor did it send out a high tank level alarm. Causing the tanks to equalize and run over. Oxy released 100 bbls produced water and 100 bbls oil, 50 bbls oil has been recovered. Leak ran off location about 2/10 of a mile. Talon will be going out to do some initial delineation, a c141 will follow.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle

Warren, JeanMarie, EMNRD

From:

Warren, JeanMarie, EMNRD

Sent:

Tuesday, December 10, 2013 2:58 PM

To:

Kimberly Wilson (kwilson@talonlpe.com)

Cc:

Bratcher, Mike, EMNRD; Christopher Jones (Christopher_Jones@oxy.com)

Subject:

McKittrick Hills CTB

Good Afternoon Kimberly,

The initial data entry is complete for this release. The remediation permit for the release date of $\frac{12/8}{13}$ is: $\frac{2RP-2107}{12}$

Have a great evening.

Jean-Marie Warren
Business Operations Specialist
NM-OCD, Artesia
District II
811 S. First St.
Artesia, NM 88210
(575) 748-1283 ext. 101

1