

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
APR 17 2014
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

n h m p 1412136548

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL Keel B #10	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05110
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter B	Section 08	Township 17S	Range 31E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.85446 Longitude: -103.88899

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 5 bbls	Volume Recovered: 5 bbls
Source of Release: Fiber glass pipeline	Date and Hour of Occurrence: 04/13/2014	Date and Hour of Discovery: 04/13/2014 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 04/15/2014 0715	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: received alarm for pump dwn at keel west water station noticed psi on header and control panel lower than usual noticed line 4 psi drop quick closed header line #4 started walking out lines going west to find leak found two leaks on the same trunk line north 100' of the Keel B #10

Describe Area Affected and Cleanup Action Taken.* : first leak on line is 5 X 5 second leak is located about 400' east of the Keel B # 10 on the same right of way spill is 5 X 5, had crew digging out line and found that line was dripping from collar on both spots

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: <i>[Signature]</i>	
Title: Construction Foreman II	Approval Date: <i>5/1/14</i>	Expiration Date: <i>NA</i>
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/16/2014 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets, if Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN:
6/1/14
2RP-2275

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Thursday, April 17, 2014 8:05 AM
To: Bratcher, Mike, EMNRD; mburton@blm.gov
Cc: Callahan, Terry; Moreno, Laura; Butters, Thomas; Gonzales, EL; Wall, Fred; Hickert, Aaron; smcgee@diversifiedfsi.com; aruth@diversifiedfsi.com; mpatterson@diversifiedfsi.com; Natalie Gladden (ngladden@diversifiedfsi.com); rpons@diversifiedfsi.com
Subject: Linn- Keel JL B #10 4-13-14
Attachments: Keel JL B #10 4-13-14.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.