625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 11 S. First St., Artesia, NM 88210 HOBBS OCD ^{Energy Miner}	e of New Mex rals and Natura	al Resources		Form C-14 Revised August 8, 201
District III Oil Con	nservation Div		Submit 1 Copy	to appropriate District Office i to cordance with 19.15.29 NMAC
000 Rio Brazos Road, Aztec, NM 87410 District IV NOV 3 0 2011 1220 S	outh St. Franc	cis Dr.	ac	cordance with 19.15.29 NMAC
	ta Fe, NM 875			
RERelease Notifica	tion and Co	orrective A	ction	
• ••	OPERA			al Report 🔲 Final Rep
Name of Company Nadel and Gussman, HEYCO, LLC Address PO Box 1936, Roswell, NM 88202-1936		eith Cannon/Tan No. (575) 623-		,
Facility Name Young Deep Unit #13		be Production	0001	
Surface Owner BLM Mineral Owner	ner BIM			. 30-025-28966
			AFINO	. 50-025-28900
	Vorth/South Line	LEASE Feet from the	East/West Line	County
C 9 18S 32E 660'	North	1980'	West Line	Lea
		<u> </u>	l	L
Latitude	Longitud	le		
NATU	RE OF REL	EASE		
Type of Release Oil		f Release 3 BBLS		Recovered 0
Source of Release Well Was Immediate Notice Given?	Date and H If YES, To	Hour of Occurrence	be Date and	Hour of Discovery
Yes No X Not Requ				
By Whom?	Date and I	Hour		
Was a Watercourse Reached?	If YES, V	If YES, Volume Impacting the Watercourse.		
Describe Cause of Problem and Remedial Action Taken.*				
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown t Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w			n.	·
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown t Describe Area Affected and Cleanup Action Taken.*			n.	
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown t Describe Area Affected and Cleanup Action Taken.*	e to the best of my ase notifications a by the NMOCD m ediate contaminat	o blaze. knowledge and und perform correct barked as "Final R ion that pose a thr	inderstand that purs tive actions for reli- eport" does not reli- reat to ground water	eases which may endanger ieve the operator of liability r, surface water, human health
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown the Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain rele public health or the environment. The acceptance of a C-141 report I should their operations have failed to adequately investigate and rem or the environment. In addition, NMOCD acceptance of a C-141 rep federal, state, or local laws and/or regulations.	e to the best of my ase notifications a by the NMOCD m ediate contaminat	o blaze. knowledge and u nd perform correc narked as "Final R ion that pose a thr ye the operator of	inderstand that purs tive actions for reli- eport" does not reli- reat to ground water	eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown to Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain rele public health or the environment. The acceptance of a C-141 report I should their operations have failed to adequately investigate and rem or the environment. In addition, NMOCD acceptance of a C-141 rep	e to the best of my ase notifications a by the NMOCD m ediate contamination port does not reliev	o blaze. knowledge and u nd perform correc narked as "Final R ion that pose a thr ye the operator of	inderstand that purs ctive actions for rel- ceport" does not relive responsibility for c SERVATION	eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown to Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain rele public health or the environment. The acceptance of a C-141 report I should their operations have failed to adequately investigate and rem or the environment. In addition, NMOCD acceptance of a C-141 rep federal, state, or local laws and/or regulations. Signature: Mathematical State Stat	e to the best of my ase notifications a by the NMOCD m ediate contamination port does not reliev	whowledge and u nd perform correct parked as "Final R ion that pose a thr we the operator of OIL CON	inderstand that purs ctive actions for rel- ceport" does not relive responsibility for c SERVATION pecialist:	eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown to Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain rele public health or the environment. The acceptance of a C-141 report I should their operations have failed to adequately investigate and rem or the environment. In addition, NMOCD acceptance of a C-141 rep federal, state, or local laws and/or regulations. Signature: Jaw Jaw Printed Name: Lori Cox	rater with 3% micr e to the best of my ase notifications a by the NMOCD m ediate contamination out does not reliev Approved by Approval Da Conditions o	to blaze. knowledge and u nd perform correct barked as "Final R ion that pose a thr ve the operator of <u>OIL CON</u> Environmental S te: $Z - 10 - 14$ f Approval:	inderstand that purs ctive actions for rel- ceport" does not relive responsibility for c SERVATION pecialist: Expiration	eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION Date: 9-12-14
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown the Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain rele public health or the environment. The acceptance of a C-141 report I should their operations have failed to adequately investigate and rem or the environment. In addition, NMOCD acceptance of a C-141 rep federal, state, or local laws and/or regulations. Signature: Jaw Jaw Printed Name: Lori Cox Title: Production Analyst E-mail Address: lcox@heycoenergy.com Date: 11/28/11 Phone: (575) 623-6601	rater with 3% micr e to the best of my ase notifications a by the NMOCD m ediate contamination out does not reliev Approved by Approval Da Conditions o	to blaze. knowledge and u nd perform correct barked as "Final R ion that pose a thr ve the operator of <u>OIL CON</u> Environmental S te: $Z - 10 - 14$ f Approval:	inderstand that purs ctive actions for rel- ceport" does not relive responsibility for c SERVATION pecialist: Expiration	eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION Date: 9-12-14
Describe Cause of Problem and Remedial Action Taken.* Hole in flow line. Flow line repaired. Occurred 11/24/11, unknown the Describe Area Affected and Cleanup Action Taken.* Pasture-remediation, clean up impacted area w/100 BBLS of fresh w I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain rele public health or the environment. The acceptance of a C-141 report I should their operations have failed to adequately investigate and rem or the environment. In addition, NMOCD acceptance of a C-141 rep federal, state, or local laws and/or regulations. Signature: Jaw Jaw Printed Name: Lori Cox Title: Production Analyst E-mail Address: lcox@heycoenergy.com	rater with 3% micr e to the best of my ase notifications a by the NMOCD m ediate contamination out does not reliev Approved by Approval Da Conditions o	to blaze. knowledge and u nd perform correct harked as "Final R ion that pose a thr te the operator of OIL CON Equironmental S te: $Z - 10 - 14$ f Approval: Z - 10 - 14 f Approval: Z - 10 - 14	inderstand that purse ctive actions for reli- ceport" does not reli- responsibility for c SERVATION pecialist: Expiration	eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION Date: 9-12-14