District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

JUL 16 2014

RECEIVED

Form C-141 Revised August 8, 2011

NNSubmin Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

nHMPI						<b>OPERA</b>			Initia	al Report		Final Re	eport	
Name of Co		Oxy Permia	16699		Contact Chancey Summers									
		tanolind Rd,	Telephone No. (575) 397-8216											
Facility Nan	ne Ama	x 24 Federal	Facility Type Well											
Surface Owner BLM Mineral Owner							API No. 30-015-27411							
LOCATION OF RELEASE														
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County				
K	24	23S	31E	1650	(	South	1650	w	est	Eddy County, NM				
			1	Latitude <u>N</u> 32,2	8728°	Longitu	de <u>W 103.7347:</u>	<u>5°</u>						
NATURE OF RELEASE														
Type of Release Oil and produced water							Volume of Release 4 bbls oil, Volume Recovered 6 bbls produced water 0 bbls							
Source of Release External corrosion on piping coming off stuffing box on the well head							Date and Hour of Occurrence O7/10/2014  Date and Hour of Discovery							
Was Immediate Notice Given?							If YES, To Whom?							
☐ Yes ☐ No ☐ Not Required							Mike Bratcher-NMOCD; Sol Hughes- BLM							
By Whom? Jennifer Gilkey, BBC International							Date and Hour 07/11/2014 @ 3:40 pm							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No														
If a Watercou	rse was Im	pacted, Descri	be Fully.*	k										
													.	
D 11 0	675 1.1	1.5	** * *											
Describe Cau	se of Proble	em and Reme	dial Action	n Taken.*										
External corre	osion on pip	oing coming o	ff the stuf	fing box on the w	ell head	caused 4 bbls	s of oil and 6 bbls	of produ	ced water	to leak onto	the gr	ound. No	,	
External corrosion on piping coming off the stuffing box on the well head caused 4 bbls of oil and 6 bbls of produced water to leak onto the ground. No fluids were recovered and the piping was repaired or replaced.														
Describe Area Affected and Cleanup Acrion Taken.*														
The affected of	seas la anne	avimatalı 60'	v 00'an f	ha nauth aida af il	المحمداء	· · · · · · · · · · · · · · · · · · ·	Elagation into the		D	مما الشعم مما			i	
				he north side of the NMOCD and the		on running of	t location into the	e pasture,	Remedia	tion will be c	ompie	etea in		
I hereby certif	fy that the i	nformation gi	ven above	is true and comp	lete to th	e best of my	knowledge and u	nderstand	that purs	uant to NMC	CD ru	iles and		
regulations all	l operators	are required to	o report an	id/or file certain r	elease no	otifications ar	id perform correc	tive actio	ns for rele	eases which r	nay er	danger	i	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health														
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
federal, state,	or local lay	vs and/or regu	lations.			·- ·								
							OIL CONS	SERV <i>A</i>	<u>ATION</u>	<u>DIVISIO</u>	<u>N</u>			
Signature:									,/		)			
							Approved by Environmental Specialist:							
Printed Name	: Chance	y Summers							1/2	1/1	_			
Title: HES Advisor A							Approval Date: 7/21/14/ Expiration Date: NA							
E-mail Addres	ee Chan	cey.Summers(	മിമ <b>യ</b> ം			Panditions - 6	Ammoreli							
L-man Addres	33. <u>CHAI</u> II		∞υλγ.cuii •	<u> </u>		Conditions of	Approval: per UCD Rule	& Guide	lines. &	Attached				
Date:	<u> </u>	6-14	Phone:	(575) 397-821										
Attach Addit	ional Shee	ts If Necessa		— іік	like approval by BLM. SUBMIT REMEDIATION  PROPOSAL NO LATER THAN: 700 7379									
						PROPOSAL NO LATER THAN: ZRP- 2379								

## Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Wednesday, July 16, 2014 9:35 AM

To:

Bratcher, Mike, EMNRD; shughes@blm.gov

Cc:

C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject:

Initial C-141, Amax 24 Federal #9

**Attachments:** 

Initial C-141, Amax 24 Federal #9.pdf

Attached is the initial C-141 for a leak that occurred at the Amax 24 Federal #9 on 07/10/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com