

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JAN 27 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1502840360

Name of Company Burnett Oil Co., Inc. <i>3080</i>		OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 801 Cherry Street - Suite 1500, Ft. Worth, TX 76102		Contact Leslie Garvis
Facility Name Gissler B 3-3 Tank Battery		Telephone No. 817-583-8730
		Facility Type Tank Battery
Surface Owner BLM	Mineral Owner BLM	API No. Lease # NMNM-2748

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	17S	30E	441'	South	467'	West	Eddy

Latitude *32.84360* Longitude *103.949126*

NATURE OF RELEASE

Type of Release Fire	Volume of Release approx: 350 bbls	Volume Recovered None - burned
Source of Release Heater Treater Fire	Date and Hour of Occurrence 1/19/15 1716 MST	Date and Hour of Discovery 1/19/15 1716 MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - J. Amos; OCD - H. Patterson (By Voice Mail and Email)	
By Whom? Leslie Garvis	Date and Hour 1/19/15 approx 1800 MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The fire is believed to have started in the main production heater treater and spread to the other heaters and separators. No tanks were involved. Flowlines were also destroyed. There was a release of approximate 350 bbls of liquid (combination of oil and water) but there is no way for us to determine the amounts of each as the fluid burned during the fire.

Describe Area Affected and Cleanup Action Taken.*

Soil samples have been taken. Approximately 2' of material will be removed and hauled to disposal. Once the material has been removed, the pad will be rebuilt with a 20 mil liner installed. The remaining impact will be left in place, and will be addressed after the battery has been rebuilt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>		OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis		Approved by Environmental Specialist: <i>H. Patterson</i>	
Title: Regulatory Coordinator		Approval Date: <i>1/28/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: lgarvis@burnettoil.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines attached <input type="checkbox"/>	
Date: 1/27/15	Phone: 817-583-8730	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *2/28/15*

2RP-2763

Patterson, Heather, EMNRD

From: Leslie Garvis <lgarvis@burnettoil.com>
Sent: Tuesday, January 27, 2015 12:49 PM
To: Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Kyle Adams; Johnny Titsworth; Walter Glasgow; Bratcher, Mike, EMNRD
Subject: RE: Gissler 3-3 Battery - Initial C-141
Attachments: 2015.01.27 GB 3-3 C-141 Initial.pdf

Attached you will find the initial C-141 from the fire at the Gissler 3-3 Battery.

Please let me know if you have any questions or need any further information.

Thank you,

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL CO., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM

From: Johnny Titsworth
Sent: Tuesday, January 27, 2015 1:09 PM
To: Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Kyle Adams; Leslie Garvis
Subject: Gissler 3-3

Heather/Jim

We had Diversified take a composite sample of the areas of SP-2 & SP-3, and ran the PID. The reading that we got back was 69.4, which is below the acceptable level (100). We have removed approximately 2' in the areas of SP-2, SP-3, and some of SP-5. The liner is in the process of being installed, and the pad will be rebuilt. The area is to be expanded to approximately 150' x75' south of where the berms divided the tanks and the heater treaters. The areas of SP-1, SP-5, & SP-6 will be addressed once the location has been put back into service. After the location has been put back into service, we can meet on location to discuss the best way to proceed with the remaining areas to be remediated. If there is anything else that you need or that we can do for you, let us know. Thanks

Johnny Titsworth
HSE COORDINATOR

BURNETT OIL CO., INC.
24 Smith Road, Suite 100
Midland, TX 79705
DIRECT LINE: (432)-614-0531
MOBILE: (432)-425-2891
EMAIL: jtitsworth@burnettoil.com

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.