LOGGED IN MS

ABOVE THIS LINE FOR DIVISION USE ONLY

### NEW MEXICO OIL CONSERVATION DIVISION

- Engineering Bureau -

1220 South St. Francis Drive, Santa Fe, NM 87505



Jicarilla C #4F

24-26N-5W

# ADMINISTRATIVE APPLICATION CHECKLIST

,	I IIO CHECKLIOT IO W	WHICH REQUIRE PROCESSING AT TI		O AND ILEGULATIONS			
Applid	[DHC-Dow [PC-Po	s:  ndard Location] [NSP-Non-Standard P  nhole Commingling] [CTB-Lease Cor ool Commingling] [OLS - Off-Lease S [WFX-Waterflood Expansion] [PMX- [SWD-Salt Water Disposal] [IPI- lified Enhanced Oil Recovery Certifica	mmingling] [PLC-Pool/Lease Con torage] [OLM-Off-Lease Measure Pressure Maintenance Expansion] -Injection Pressure Increase]	nmingling] ement]			
[1]	TYPE OF AI [A]	PPLICATION - Check Those Which A Location - Spacing Unit - Simultaneo X NSL NSP SD					
	Check [B]	Cone Only for [B] or [C] Commingling - Storage - Measuremen DHC CTB PLC					
	[C]	Injection - Disposal - Pressure Increas  WFX PMX SWD	e - Enhanced Oil Recovery IPI  EOR PPR				
	[D]	Other: Specify					
[2]	NOTIFICATION REQUIRED TO: - Check Those Which Apply, or □ Does Not Apply [A] Working, Royalty or Overriding Royalty Interest Owners						
	[B]	X Offset Operators, Leaseholders or	Surface Owner				
	[C]	Application is One Which Requi	res Published Legal Notice				
	[D]	Notification and/or Concurrent A U.S. Bureau of Land Management - Commissioner	approval by BLM or SLO of Public Lands, State Land Office				
	[E]	For all of the above, Proof of No	tification or Publication is Attached,	and/or,			
	[F]	☐ Waivers are Attached					
[3]		CURATE AND COMPLETE INFOR ATION INDICATED ABOVE.	MATION REQUIRED TO PRO	CESS THE TYPE			
[4] appro applic	val is <b>accurate</b> a	TION: I hereby certify that the informand complete to the best of my knowled quired information and notifications are	ge. I also understand that no action	for administrative will be taken on this			
		Statement must be completed by an individua	al with managerial and/or supervisory capa	acity.			
Richa	ard Corcoran	Lichard Corcora	Land Manager	8-23-05			
Print o	or Type Name	Signature	Title	Date			
			Rich.corcoran@cdxgas.com e-mail Address	<u> </u>			
			Cilian Addiess				



CDX Gas, LLC 2010 Afton Place Farmington, NM 87401 Main: 505-326-3003 Fax: 505-325-4007

AUG 2 9 2005

**OIL CONSERVATION** DIVISION

August 23, 2005

**New Mexico Oil Conservation Division** Attn: Michael E. Stogner 1220 South St. Francis Drive Santa Fe, New Mexico 87505

RE:

ADMINISTRATIVE APPROVAL OF UNORTHODOX LOCATIONS

JICARILLA C #4F,

Section 24, T26N-R5W

JICARILLA A #7F,

Section 17, T26N-R5W

JICARILLA 151 #7G, Section 4, T26N-R5W

JICARILLA 102 #14F, Section 9, T26N-R4W

JICARILLA 102 #9F, Section 4, T26N-R4W

JICARILLA 102 #8F, Section 3, T26N-R4W

RIO ARRIBA COUNTY, NEW MEXICO

### Dear Mr. Stogner:

CDX Rio, LLC hereby requests Administrative Approval for the following Unorthodox Locations all proposed as Blanco Mesaverde/Basin Dakota commingled wells except the Jicarilla 151 #7G which will be completed in the Dakota formation only; under the provisions of New Mexico Oil Conservation Division (NMOCD) Order R-10987-A, Basin Dakota pool and Order R-10987-B, Blanco Mesaverde pool.

Well Name & Number	Bottom Hole / (Surface) Location	Sec-Twn-Rng	Formations / Spacing		
1) Jicarilla C #4F	660 FSL, 2100 FWL	24-T26N-R5W	MVRD - W/2 DKOT - W/2		
2) Jicarilla A #7F	660 FNL, 2055 FWL	17-T26N-R5W	MVRD- W/2 DKOT- W/2		
3) Jicarilla 151 #7G	1470 FNL, 2305 FWL	4-T26N-R5W	DKOT - W/2		
4) Jicarilla 102 #14F	120 FNL, 660 FWL	9-T26N-R4W	MVRD - N/2 DKOT - W/2		
5) Jicarilla 102 #9F	585 FNL, 760 FEL	4-T26N-R4W	MVRD- E/2 DKOT - E/2		
6) Jicarilla 102 #8F	660 FSL, 2100 FEL (430 FSL, 965 FEL)	3-T26N-R4W	MVRD- E/2 DKOT - S/2		

Each of the proposed locations is a standard 320 acre gas spacing unit and each well is to be located at the spot set out above. The location of each proposed test was selected to optimize recovery from the Dakota formation. Drainage areas are elliptical in shape and have been determined from a study done on Township 26 North Ranges 4 and 5 West and are more specifically set out in the attached Geological/Engineering report. In every case, except the Jicarilla 102 #9F, the proposed location encroaches on CDX Rio, LLC operated wells with the same ownership as the offending well. In addition to reservoir considerations the topography at Honolulu Mesa is very rough and the abundance of Cultural Resources made locating wells where there would not be significant over lap of existing drainage patterns unattainable.

#### Jicarilla C #4F

The proposed well would be the third Dakota and second Mesaverde well(s) in the W/2 of Section 24-T26N-R5W. The Jicarilla C #4 (API #30-039-08139) located 1,650' FNL and 1,650' FWL of Section 24-T26N-R5W, was drilled to a total depth of 7,680', completed in the Mesaverde and Dakota formations in August of 1966, and has cumulatively produced 2,611,071 MCFG through June of 2005. The Jicarilla C #4E (API #30-039-22298) located 790' FSL and 990' FWL of Section 24-T26N-R5W, was drilled to a total depth of 7,525', completed in the Dakota formation on March 9, 1981 and has produced 1,022,372 MCFG through June of 2005. CDX Rio, LLC is the operator of the E/2 of Section 24-T26N-R5W, being the direction of encroachment; which has the same ownership as the W/2 of said Section 24, consequently no other offsetting operators are affected.

#### Jicarilla A #7F

The proposed well would be the third Dakota and second Mesaverde well(s) in the W/2 of Section 17-T26N-R5W. The Jicarilla A #7 (API #30-039-08097) located 1,595' FSL and 900' FWL of Section 17-T26N-R5W, was drilled to a total depth of 7,670', completed in the Dakota formation on October 6, 1966, and has cumulatively produced 563,205 MCFG through June of 2005. The Jicarilla A #7E (API #30-039-22896) located 940' FNL and 1,000' FWL of Section 17-T26N-R5W, was drilled to a total depth of 7,650', completed in the Dakota formation on September 13, 1982 and in the Mesaverde on July 8 2002, and has produced 571,490 MCFG through June of 2005.

CDX Rio, LLC is the operator of the E/2 of Section 17-T26N-R5W, being the direction of encroachment; which has the same ownership as the W/2 of said Section 17; consequently no other offsetting operators are affected.

#### Jicarilla 151 #7G

The proposed well would be the third Dakota well in the W/2 of Section 4 -T26N-R5W. The Jicarilla 151 #7 (API #30-039-21675) located 790' FNL and 790' FWL of Section 4 -T26N-R5W, was drilled to a total depth of 7,610', completed in the Dakota formation on October 25, 1978, and has cumulatively produced 657,208 MCFG through June of 2005. The Jicarilla 151 #7E (API #30-039-23163) located 1,030' FNL and 1,050' FWL of Section 4 -T26N-R5W, was drilled to a total depth of 7,723', completed in the Dakota formation on August 12, 1983, and has produced 710,899 MCFG through June of 2005.

CDX Rio, LLC is the operator of the E/2 of Section 4 -T26N-R5W, being the direction of encroachment; which has the same ownership as the W/2 of said Section 4, consequently no other offsetting operators are affected.

Mode to his in short for the form of the basin Mu. are basin Mu. are Blanco Hervals.

#### Jicarilla 102 #14F

The proposed well would be the third Dakota and Mesaverde well(s) in its respective proration unit: consisting of the W/2 of Section 9-T26N-R4W for the Basin Dakota formation and the N/2 of Section 9 for the Blanco Mesaverde formation. The Jicarilla 102 #14 (API #30-039-06594) located 1,620' FNL and 1,730' FWL of Section 9 -T26N-R4W, was drilled to a total depth of 8,320', completed in the Dakota formation on October 4, 1963, and has cumulatively produced 1,480,920 MCFG through June of 2005. The Jicarilla 102 #14E (API #30-039-22457) located 1,110' FSL and, 800' FWL of Section 9-T26N-R4W, was drilled to a total depth of 8.254'. completed in the Dakota formation on October 9, 1980, and has cumulatively produced 585,547 MCFG through June of 2005. The Jicarilla 102 #29 (API #30-039- 21581) located 1,560' FNL and 1,790' FEL of Section 9 -T26N-R4W, was drilled to a total depth of 6,250', completed in the Mesaverde formation on April 3, 1978, and has cumulatively produced 527,294 MCFG through December of 2003. The Jicarilla 102 #29A (API #30-039-22931) located 910' FNL and 1,740' FWL of Section 9 -T26N-R4W, was drilled to a total depth of 7,649', completed in the Mesaverde formation on August 2, 1982, and has cumulatively produced 692,919 **MCFG** through June of 2005.

CDX Rio, LLC is the operator of All of Section 4 -T26N-R4W, being the direction of encroachment; which has the same ownership as the W/2 and N/2 of Section 9, T26N-R4W, consequently no other offsetting operators are affected.

#### Jicarilla 102 #9F

The proposed well would be the third Dakota and Mesaverde well(s) in the E/2 of Section 4 - T26N-R4W. The Jicarilla 102 #9 (API #30-039-06715) located 1,600' FNL and 1,800' FEL of Section 4 -T26N-R4W, was drilled to a total depth of 8,416', completed in the Dakota formation on June 30, 1963, and has cumulatively produced 2,221,652 MCFG through June of 2005. The Jicarilla 102 #9E (API #30-039-22456) located 970' FSL and 920' FEL of Section 4 -T26N-R4W, was drilled to a total depth of 8,150', completed in the Dakota formation on October 17, 1980, and has cumulatively produced 1,817,603 MCFG through June of 2005. The Jicarilla 102 #5 (API #30-039-06718) located 1,450' FNL and 1,450' FEL of Section 4 -T26N-R4W, was drilled to a total depth of 6,448', completed in the Mesaverde formation on September 19 1957, and has cumulatively produced 744,680 MCFG through June of 2005. The Jicarilla 102 #5A (API #30-039-23197) located 1,120' FSL and 790' FEL of Section 4 -T26N-R4W, was drilled to a total depth of 6,088', completed in the Mesaverde formation on October 5, 1983, and has cumulatively produced 444,000 MCFG through June of 2005.

Burlington Resources is the operator of All of Section 33-T27N-R4W, being the direction of encroachment.

Moving this location 75' north of the window was necessary due to Archeological consideration in addition to the reservoir conditions depicted on the attached plats.

#### Jicarilla 102 #8F

The proposed well would be the third Dakota and fourth Mesaverde well(s) in its respective proration unit; consisting of the S/2 of Section 3-T26N-R4W for the Basin Dakota formation and the E/2 of Section 3 for the Blanco Mesaverde formation. This well is at a standard location for the Dakota formation being the S/2 of section 3 but non-standard for the E/2 of Section 3 Mesaverde spacing unit. The Jicarilla 102 #8 (API #30-039-06679) located 1,790' FSL and 1,480' FWL of Section 3 -T26N-R4W, was drilled to a total depth of 8,120', completed in the Dakota formation on June 12, 1963, and has cumulatively produced 3,934,418 MCFG through June of 2005. The Jicarilla 102 #8E (API #30-039-22454) located 1,700' FSL and 940' FEL of Section 3 -T26N-R4W, was drilled to a total depth of 8,096', completed in the Mesaverde and Dakota formations on October 31, 1980, and has cumulatively produced 2,202,424 MCFG through June of 2005. The Jicarilla 102 #8A (API #30-039- 23195) located 1,120' FNL and 1,080' FEL of Section 3 -T26N-R4W, was drilled to a total depth of 6,089', completed in the

formation on September 19 1983, and has cumulatively produced 278,679 MCFG through June of 2005. The Jicarilla 102 #7 (API #30-039-06709) located 1,850' FNL and 2,390' FEL of Section 3 -T26N-R4W, was drilled to a total depth of 8,192', completed in the Mesaverde formation on December 16, 2002, and has cumulatively produced 163,675 MCFG through June of 2005.

CDX Rio, LLC is the operator of All of Section 10-T26N-R4W, being the direction of encroachment; which has the same ownership as the E/2 and S/2 of Section 3, T26N-R4W; consequently no other offsetting operators are affected.

Attached is a well location plat showing dedicated acreage (C-102), a topographic plat of the area, a map showing all offsetting owners and our Geologic/Engineering explanation of the reservoir considerations establishing the increased recovery that we expect to gain by moving the proposed wells to non-standard locations.

Your favorable consideration of this request would be appreciated.

Sincerely,

Richard Corcoran Land Manager



To:

Mike Stogner

From:

Rod Seale, Senior Petroleum Engineer and Peter Kondrat, Senior Geologist

Subject: Approval Request of Mesaverde-Dakota Formations Unorthodox Infill Locations due to

Reservoir Considerations

Location: CDX Rio, LLC Leasehold, Jicarilla Apache Nation, San Juan Basin

**Date:** August 22, 2005

#### **Application:**

CDX Rio, LLC respectfully requests the approval of the following listed unorthodox Mesaverde-Dakota Formations infill locations due to reservoir considerations.

Well Name & Number	Spot of Bottom Hole Location	Sec-Twn-Rng	Formations		
1) Jicarilla C #4F	660 FSL, 2100 FWL	24-T26N-R5W	MVRD-DKOT		
2) Jicarilla A #7F	660 FNL, 2055 FWL	17-T26N-R5W	MVRD-DKOT		
3) Jicarilla 151 #7G	1470 FNL, 2305 FWL	4-T26N-R5W	DKOT		
4) Jicarilla 102 #14F	120 FNL, 660 FWL	9-T26N-R4W	MVRD-DKOT		
5) Jicarilla 102 #9F	585 FNL, 760 FEL	4-T26N-R4W	MVRD-DKOT		
6) Jicarilla 102 #8F (Directional Well)	660 FSL, 2100 FEL	3-T26N-R4W	MVRD-DKOT		

#### Summary:

CDX Rio, LLC is continuing its Mesaverde-Dakota 80-acre increased density infill development program of its San Juan Basin Tapicito Project located in the Jicarilla Apache Nation, Rio Arribia County, New Mexico. CDX is currently permitting both standard and non-standard locations to fulfill the development program. The proposed unorthodox gas well locations are necessitated by a combination of topographic, engineering and geologic factors.

Utilizing geologic and engineering data, CDX has completed a detailed study identifying the most optimal locations for Mesaverde and Dakota Formation infill wells. These locations are defined as optimal because they ensure maximum recovery of reserves and minimize waste.

CDX has constructed various maps for the Mesaverde and Dakota Formations that depict:

- 1) Bulk volume hydrocarbon feet
- 2) Original GIP (OGIP)
- 3) Estimated Ultimate Recovery (EUR)
- 4) Remaining GIP (RGIP)
- 5) EUR Drainage Volume Ellipses that depict Producing Characteristics
- 6) Optimal Infill Development Locations

#### **Exhibits**

Attached are two sets of maps for each proposed unorthodox infill location.

- Land plats that show CDX's leasehold and the proposed new drill bottom-hole locations.
- 2) Dakota Formation EUR drainage volume ellipses that depict the producing characteristics of the existing wells and also the proposed unorthodox infill locations. The volume ellipses acreage was computed using bulk volume hydrocarbon feet and EUR.
  - a. Both Mesaverde and Dakota Formations have fracture-permeability anisotropy resulting in elliptical drainages. Following the area's best practices the elliptical drainages were drawn at a 3.7:1 aspect ratio and with a maximum horizontal permeability direction of N10°.



b. The location of the Dakota Formation drainage ellipses is the primary reason for permitting non-standard locations. Dakota Formation infill locations were selected to optimize recovery for the rock unit.

#### References

NMOCD Case Number 12508; Order Number R-11503

NMOCD Case Number 12745; Order Number R-10987-B; 2002; To Amend the Special Rules and Regulations for the Basin-Dakota Pool to Increase Well Density and Amend the Well Location Requirements; Burlington Resources Oil and Gas Company and Conoco Incorporated; 15 pages

SPE Paper #60288; 2000; Producing Characteristics and Drainage Volume of Dakota Reservoirs, San Juan Basin; Arild Sunde, Her-Yuan Chen, Lawerence W. Teufel; 10 pages

SPE Paper #77742; 2002; An Effective Technique of Estimating Drainage Shape, Magnitude and Orientation in a Low-Permeability Gas Sand; Ryan L. Robinson and Thomas W. Engler; 8 pages

SPE Paper #39974; 1998; Drainage Efficiency in Naturally Fracture Tight Gas Sandstone Reservoirs; H. Harstad, L.W. Teufel and J.C. Lorenz; 11 pages

SPE Paper #39911; 1998; Potential for Infill Drilling in a Naturally Fractured Tights Gas Sandstone Reservoir; H. Harstad, L.W. Teufel and J.C. Lorenz; 11 pages

SPE Paper #38580; 1997; Methodology to Optimize Completions in the Mesaverde Formation, San Juan Basin, New Mexico; Brian P. Ault, Earuch F. Broacha and David L. Holcomb; 20 pages

SPE Paper #60295; 2000; Influence of Permeability Anisotropy and Reservoir Heterogeneity on Optimization of Infill Drilling in Naturally Fractured Tight-Gas Mesaverde Sandstone Reservoirs, San Juan Basin; H.K. Al-Hadrami and L.W. Teufel; 12 pages

SPE Paper #68598; 2001; Practical Methods to High-Grade Infill Opportunities Applied to the Mesaverde, Morrow and Cotton Valley Formations; J.W. Hudson, J.E. Jochen, J.P. Spivey; 11 pages

SPE Paper #21484; 1991; The Impact of Improved Technology on Potential Tight Gas Reserves in the San Juan Basin; M.R. Haas and T.E. Crist; 14 pages



CDX Gas, LLC 2010 Afton Place Farmington, NM 87401 Main: 505-326-3003 Fax: 505-325-4007

August 23, 2005

Ms. Linda Dean Burlington Resources 3401 E. 30<sup>th</sup> Farmington, New Mexico 87402

Re:

ADMINISTRATIVE APPROVAL OF UNORTHODOX LOCATION

JICARILLA 102 #9F 585' FNL & 760' FWL SECTION 4-T26N-T4W

RIO ARRIBA COUNTY, NEW MEXICO

Dear Ms. Dean:

CDX RIO, LLC has filed with the New Mexico Oil Conservation Division (NMOCD), an application for the Administrative Approval of an unorthodox location for its Jicarilla Apache 102 #9F. A copy of the application has been attached for your review.

If you have no objection to this unorthodox location, please sign three copies of the attached waiver, return one executed copy to the NMOCD at 1220 South Saint Frances Drive in Santa Fe, New Mexico 87505, one copy to our office and retain one copy for your files.

Your cooperation in this matter is appreciated.

Land Manager	Sincerely,  Lichard Occoran  Richard P. Corcoran
Land Manager	Richard P. Corcoran
•	Land Manager

WAIVER

<u>Burlington Resources</u> hereby waives objection to the above referenced Application for Unorthodox location for CDX RIO, LLC's Jicarilla 102 #9F well.

Date: \_\_\_\_\_\_ By: \_\_\_\_\_\_

New Mexico Oil Conversation Division Attention: Michael E. Stogner 1220 South St. Francis Drive Santa Fe, New Mexico 87505

## State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised June 10, 2003 Submit to Appropriate District Office

> State Lease - 4 Copies Fee Lease - 3 Copies

BY DBL. PROP.

\$ 88-51-57 E

☐ AMENDED REPORT


	SO Bath R. !	rences Ir.,		WELL I	OCATIO	N AND A	CREAGE DED	ICATION P	LAT		
	Mi e	Number			Pool Code			*Pool Nam	16		
30=039= 723				7231	72319/71599 Blanco Mesaverde/Basin Dakota Property Name					Well Number	
Property Code					· · · · · · · · · · · · · · · · · · ·					4F	
	TOGRAD No					*Operator CDX GAS				•	Elevation
	22237	74					·			<u></u>	6588'
				- <del></del>	V . 8 V2	<sup>10</sup> Surface		W. 1 4 12.	9-1-1-1-		12
	UL or lot no.	Section 24	Township 26-N	Range 5-W	Lot Idn	Feet from the 660	North/South line SOUTH	Feet from the 2100	East/Ve WE	ST	RIO ARRIBA
		<u> </u>		11 Bott	om Hole	Location	If Different Fr	om Surface	·		1
60	UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/We	st line	County
				<sup>25</sup> Joint or	Ind(i)	<sup>24</sup> Consolidation	<u></u>	25 Order No.			<u>L</u>
	Dedicated Acres			JOINE OF		COMBURGACION	Code	Ottor No.			
1	DK - W/3			COLONIEL	Mo mili	C COMPTERM	CAT TELEVISION ATT	TAMOUNTAING 7	747777 70	ETERT CO	
nue .	NO ALLOWA	ABLE W				INIT HAS B	ON UNTIL ALL EEN APPROVED			EEN CO	nsolidated
	CALC'D CORN BY DBL. PRO				24	Sta.	la-la-la-la-la-la-la-la-la-la-la-la-la-l	I hereby certification and comp    Continue and comp   Continue and comp   Signature   Richar   Printed Nas	rd Core	oper of my b	ETIFICATION contained herein is nousledge and bolief
200	N 00-22-51 W		LAT. 36°2 LONG. 10	28'00.4"N 07"18'44.	(NAD 8 2" W (NAI	3) D 83)		I hereby certify was plotted free	that the wo n field notes pervision, as	il location s of actual s and that the	FICATION house on this plat servers made by the scene is true and
 C/	2: ALC'D CORNE	100'	,099			,	CALC'D CORNER	A THE	12- ROFESS	ONLEGE	/

CALC'D CORNER

BY SGL. PROP.

5338.43' (C)

Certificate Number



# **CDX Rio, LLC**

# Jicarilla C #4F

### **OFFSET OPERATOR \ OWNER PLAT**

Basin Dakota/Blanco Mesaverde Formation W/2 Section 24, Township 26 North - Range 5 West Rio Arriba County, NM

