

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB152295045A

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>1924103</i>	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Hackberry 6 Fed Com #4H	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-41248

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	6	19S	31E					Eddy County, NM

Latitude N 32.69558° Longitude W 103.91203°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	8 bbls	Volume Recovered	6 bbls
Source of Release	Over pressure on the stuffing box caused the packing to blow out of the well head	Date and Hour of Occurrence	07/19/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker and James Amos-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	07/20/2015 @ 4:06 pm	NM OIL CONSERVATION ARTESIA DISTRICT AUG 14 2015 RECEIVED	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

Describe Cause of Problem and Remedial Action Taken.*

Over pressure on the stuffing box caused the packing to blow out on the well head and spill 8 bbls of oil onto the ground. A vacuum truck recovered 6 bbls of oil and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 105' x 40' on location. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: CJ Summers	Approved by Environmental Specialist: 	
Title: HES Lead	Approval Date: 8/17/15	Expiration Date: N/A
E-mail Address: chancey_summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8-13-15	Phone: (432) 685-5824	Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/18/15

2RP-3204

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Friday, August 14, 2015 4:23 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Coyote 21 #2
Attachments: Initial C-141, Coyote 21 #2.pdf

Attached is the initial C-141 for a leak that occurred at the Coyote 21 #2 on 07/23/15 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Jennifer Gilkey <jgilkey@bbcinternational.com>
Sent: Friday, July 24, 2015 5:07 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; CJ Summers
Cc: Cliff Brunson ; Ken Swinney; Kathy Purvis
Subject: Coyote 21 #2

This is to inform you that Oxy Permian had a leak at the Coyote 21 #2 on July 23, 2015. Oxy spilled 5 bbls of oil and 30 bbls of produced water due to back pressure causing the stuffing box packing to leak on the well head. The preliminary report shows the leak measuring approximately 20' x 10' on location. A vacuum truck recovered 30 bbls of fluids. The release is located in the U/L N of Section 21, T24S, R29E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Loving, take US 285 to Malaga, turn east on Duarte Rd and go 2.5-3 miles, turn right on McDonald Rd, cross the Pecos River, turn left at the first white cattleguard and go 0.25 mile to battery and well location. API# 30-15-29864, GPS coordinates: N 32.19824° W 103.99020°

Jennifer Gilkey
Administrative Manager
BBC International, Inc.
Phone: (575) 397-6388
Fax: (575) 397-0397
E-mail: jgilkey@bbcinternational.com
1324 W. Marland Blvd.
Hobbs, NM 88240
