

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 07 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1528134977

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>240737</u>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 42	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 3001521095
------------------------	----------------	--------------------

LOCATION OF RELEASE

Unit Letter G	Section 10	Township 25S	Range 30E	Feet from the 1980	North/South Line	Feet from the 1980	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------------	-----------------------	----------------	----------------

Latitude: 32.146993 Longitude: 103.866696

NATURE OF RELEASE

Type of Release: Produced water/ Crude oil	Volume of Release: 7 barrels	Volume Recovered: 2 barrels
Source of Release: Gasket failed on FWKO	Date and Hour of Occurrence: 10-2-15 @ 3:30pm	Date and Hour of Discovery: 10-2-15 @ 4:15pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gasket on the FWKO failed releasing a combination of produced water and crude oil to the ground surface. A light mist was sprayed outside the firewall on the NW corner of the well pad. Two barrels of standing fluid was recovered from around the FWKO and heater treater area.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and recovered 2 barrels of fluid. A micro blaze crew was dispatched to location and treated the vegetation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <u>Mike Brannan</u> Approved by Environmental Specialist	
Title: Assistant Remediation Foreman	Approval Date: <u>10/8/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>10-7-15</u> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/8/15

2RP-3321

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Wednesday, October 07, 2015 11:34 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU 42
Attachments: scan.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU 42. If you have any questions please let me know.

Brad Blevins
Remediation Foreman (PLU)
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com