

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 14 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1601541742

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cypress 34 Federal #1 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-35053

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	34	23S	29E					Eddy County, NM

Latitude N 32.25497° Longitude W 103.96603°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	15 bbls oil, 25 bbls produced water	Volume Recovered	36 bbls
Source of Release	Head switch was full of trash and failed causing a tank spill	Date and Hour of Occurrence	01/05/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Kelly Jones-NMOCD		
By Whom?	Jennifer Gilkey @ BBC International	Date and Hour	01/05/2016 @ 4:55 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A head switch full of trash failed causing a tank to spill 15 bbls of oil and 25 bbls of produced water onto the ground. A vacuum truck recovered 36 bbls of fluids and the head switch was cleaned out.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 150' x 60' on location around the tanks inside the containment. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Casey Summers

Title: NM Environmental Advisor

E-mail Address: Casey.Summers@oxy.com

Date: 1-14-16

Phone: (575) 513-8289

Approved by Environmental Specialist:

Approval Date: 1/15/16

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 1/15/16

* Attach Additional Sheets If Necessary

2RP-3 447

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, January 14, 2016 4:28 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; dusty_wilson@oxy.com; Jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Cypress 34 Federal #1 CTB
Attachments: Initial C-141, Cypress 34 Federal #1 CTB.pdf

Attached is the initial C-141 for a leak that occurred at the Cypress 34 Federal #1 CTB on 01/05/2016 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Patterson, Heather, EMNRD

From: Jennifer Gilkey <jgilkey@bbcinternational.com>
Sent: Tuesday, January 05, 2016 4:55 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly
Cc: casey_summers@Oxy.com; Dusty Wilson; Frank_Barnett@oxy.com;
Jennifer_duarte@oxy.com; Cliff Brunson ; Ken Swinney; Kathy Purvis
Subject: Cypress 34 Fed #1 CTB

This is to inform you that Oxy Permian had a leak at the Cypress 34 Federal #1 CTB on January 5, 2016. Oxy spilled 25 bbls of produced water and 15 bbls of oil. The facility is a lined containment all fluids stayed in the containment. 36 bbls of fluids were recovered. The release is located in U/L P of Section 34, T23S, R29E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: At NM 128, go South on CR793 (Rawhide Rd) for 4.0 miles, turn right and go West on the main road for 3.5 miles, turn left at Oxy sign and go 2.7 miles down the main road to location on the left or North side of the road. API# 30-015-35053 GPS coordinates: N 32.25496° W -103.96596°

Jennifer Gilkey

Administrative Manager

BBC International, Inc.

Phone: (575) 397-6388

Fax: (575) 397-0397

E-mail: jgilkey@bbcinternational.com

1324 W. Marland Blvd.

Hobbs, NM 88240
