NM OIL CONSERVATION

ARTÉSIA DISTRICT

State of New Mexico Energy Minerals and Natural Resources

JUN 08 2016

Form C-141

Revised August 8, 2011

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe. NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa F. NIM 87505

Submit I Copy to appropriate District Office in **RECEIVED** ance with 19.15.29 NMAC.

Santa Fe, NM 67303													
Release Notification and Corrective Action													
$\sim \Lambda + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 +$							OPERATOR						
Name of Co		Contact: JD Machacek						· · · · · · · · · · · · · · · · · · ·					
							Telephone No.: 432-889-3928						
Well Name			,			Type: Oil							
Surface Owner: BLM Mineral Owner: I							BLM API No.: 30-015-01035						
Durace Ow	1101 , 1513)71			[Willierar C	, DIATI			JATINO	30-013-0	11055			
					OIT	N OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the	Nort			East/\	West Line County			•	
A	A 7 20-S 27-E 330					N	990	990 E Ede			1y		
L	<u></u>	I	11					<u> </u>					
			Lat	itude		Longitud	le <u>.</u>						
				NAT	URE	OF REL	EASE						
Type of Rele	ase; Leak	Volume of Release: N/A Volume Recovered: 0											
Source of Re	lease: Flow	1	Date and Hour of Occurrence: D				Date and Hour of Discovery: N/A						
Was Immedia	ota Mati (N/A	N/A If YES, To Whom?										
was immedia	are mones (11 125, 10	w HOIII!										
Required		<u> </u>] [0, [_	No Not									
By Whom?		Date and Hour											
Was a Water	course Reac	If YES, Volume Impacting the Watercourse.											
☐ Yes ☒ No													
If a Watercon	wee was Im	nacted Deccr	ibo Eully *			<u> </u>							
If a Watercourse was Impacted, Describe Fully.*													
1													
Describe Cause of Problem and Remedial Action Taken.*													
Describe Cause of Problem and Remedial Action Taken.* Flowline was punctured and then repaired,													
			•									_	
Dagariba Ara	Describe Area Affected and Cleanup Action Taken,*												
				en." spot approxima:	telv 65	i' to the SW. S	oil had noticeab	le TPH	but no veg	etation wa	s affec	ted or	
				llect TPH contar									
	C 11			* * * * * * * * * * * * * * * * * * * *						. NIL	(OCP)		
				is true and comp. d/or file certain re									
				e of a C-141 repo									
				investigate and re									
				tance of a C-141:	report	does not reliev	e the operator of	respons	ibility for co	ompliance v	vith ar	ry other	
tederal, state, or local laws and/or regulations.							OIL CONSERVATION DIVISION						
,	100	OIL CONSERVATION DIVISION											
Signature:	JT7 W	Approved by Environmental Specialist Ly Linguister											
Printed Name: It unfellow							~B 418 W		WIT Z	JETETALE	#K#	·	
7 miled Hami			- 1				1.121.1	. T	••	<u> </u>	1		
Title: Enginee/						Approval Dat	ic: (1 1 1) 1 L	0	Expiration	Date: N/F	1		
E-mail Addre	•	Conditions of Approval: Attached											
Date:	6/2/	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO											
Attach Addi			POSAL NO ADD-2010										
						LATER TH	an:	HU			UK	r Ulay	
() () () () ()	praction	· Som bli	ss less	rel er									
	0400	. Sample valed	area										
From	, execu			-									

Bratcher, Mike, EMNRD

From:

JD M. <jd@saberogv.com>

Sent:

Friday, June 03, 2016 8:28 AM

To:

Tucker, Shelly; Jones, Kellie, EMNRD; Bratcher, Mike, EMNRD

Subject:

Re: Saber OGV - Yates Federal # 1 (C-141)

Attachments:

Yates Federal # 1 - C-141 (6.2.16).pdf

Here is the signed version. Sorry about that.

Jd

On Thu, Jun 2, 2016 at 1:49 PM, JD M. < jd@saberogv.com > wrote:

Here is our initial C-141 for this well.

Please let me know if you need anything else.

J.D. Machacek

Engineer

Saber Oil & Gas Ventures, LLC

400 W. Illinois, Suite 950

Midland, TX 79701

Office: (432) 685-0169

Cell: (432) 889-3928