

Bratcher, Mike, EMNRD

From: Shoemaker, Mike <Mike.Shoemaker@dvn.com>
Sent: Wednesday, February 28, 2018 9:48 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)
Subject: Snapping 10 Federal 1H (API #30-015-37899)

Good Morning,

Devon had a release occur at 12:30 PM MST on 02/27/18. The incident is described below.

1. Snapping 10 Federal 1H (API #30-015-37899) the release occurred at the battery for this well which is located on the Ross Ranch 10 Federal 1 location (API# 30-015-29605)
 - a. The back psi valve failed on the 2 phase separator causing the vessel to swamp out causing a release and misting overspray to the pad and adjacent pasture. A total of approximately 16 bbls of oil (approximately 15.5 bbls to the pad surface and approximately 0.5 bbls overspray was released to the adjacent pasture).

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

If you have any questions please let me know.

Thanks,

Mike Shoemaker
EHS Representative

Devon Energy Corporation
6488 Seven Rivers Highway
Artesia, New Mexico 88210
575-746-5566 Office
575-513-5035 Mobile



2RP-40001
30-015-37899

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.