STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION 2040 S. PACHECO SANTA FE, NEW MEXICO 87505 (505) 827-7131

May 19, 1997

Amoco Production Company P. O. Box 606 Clayton, New Mexico 88415 Attention: Bill Prichard

Administrative Order TX-269

pVEV2005730350

Dear Mr. Prichard:

Reference is made to your request for an exception to the tubing setting requirements as contained in Division Rule 107 (j) for the below-named wells.

Pursuant to the authority granted me by Rule 107 (d) (4), you are hereby authorized to make tubingless completions in the following wells:

Well Name, Number and Location:

BDCDGU 1934 Well No. 11, API No. 30-059-20047, Unit F, Section 1, Township 19 North, Range 34 East, NMPM, Union County, New Mexico.

BDCDGU 1934 Well No. 41, API No. 30-059-20079, Unit K, Section 4, Township 19 North, Range 34 East, NMPM, Union County, New Mexico.

BDCDGU 1934 Well No. 131, API No. 30-059-20075, Unit B, Section 13, Township 19 North, Range 34 East, NMPM, Union County, New Mexico.

BDCDGU 1935 Well No. 221, API No. 30-059-20116, Unit G, Section 22, Township 19 North, Range 35 East, NMPM, Union County, New Mexico.

The Division reserves the right to rescind this authority in the event that waste appears to be resulting therefrom.

Sincerely,	
رسطوم	ing reling
William J. LeMay	/
Director	
WJL/RJ/kv	

cc: Oil Conservation Division - Santa Fe



Mr. Roy Johnson State of New Mexico Energy and Minerals Department Oil Conservation Division 2040 Pacheco Street Santa Fe, NM 87505

moce Production Company APR 17 1997 OIL CONSERVATION ENVIRION

File: BEP 0049

Ż.

Dear Mr. Johnson:

Exception to Statewide Rule 107(J) Bravo Dome Carbon Dioxide Gas Unit Well Nos. 1934-011F, 1935-221G, 1934-041K, 1934-131B Union County, New Mexico

Amoco Production Company requests an exception to Rule 107(J), in order to Bravo Dome Carbon Dioxide Gas Unit Well Numbers: 1934-011F, 1935-221G, 1934-041K, 1934-131B.

Amoco has run A 5.2" OD SDR 17 polyethlyene liner to the top of the Production Packer, thereby eliminating the need for tubing.


A well bore schematic is attached for your information and review.

Your administrative approval of this request will be appreciated. If additional information is desired, please contact me at (505)374-3053.

Yours very truly, ily E. Pruhan

Billy E. Prichard Field Foreman

Attachments



Perforations Detail

2088-94, 2099-2102, 21-25, 40-48, 52-55, 66-68, 74-76, 79-82, 84-90, 93-95, 2199-2201, 03-05, 09-13, 19-23, 25-33, 46-48, 54-56, 60-63, 69-71, 75-78, 82-91, 2308-12, w/2 JSPF Squeeze: 2376-80, 2388-98, 2403-13, 2437-42, 2470-2513, 2525-33, w/2 JSPF

Reservoir Data			
height - h, ft	100	res.press Pr.psig	260
net pay, ft	84	skin, s	-4
perm - k, md	18	frac	Yes

Well History			

HOUSPB LAN I:\common\bdome\prodengr\polybore\WELLBORE.XLS